

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW
 #14-01 ASIA SQUARE TOWER 2
 SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0323-7293

Claim Type: Third Party

Accident Date: 03/03/2023

TP Veh Reg No: SKE 9939 B

Estimate No: EST1509400

Date: 03 Mar 2023

Policy No: GA610876

Veh Reg No: **SLX496J**

Make/Model: HONDA ODYSSEY 2.4
 EX-S CVT

Chassis No: JHMRC1880JC200852

Engine No: K24W72400369

Reg. Date: 14/03/2018

Estimate Repair Cost to Vehicle No :SLX496J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
38 REAR BOOT LOWER LOCK	32.7000	1 PC	32.70	
39 REAR BOOT LAMP - LH/RH	448.0000	2 PC	896.00	
40 REAR BOOT ODYSSEY WORDING	53.6000	1 PC	53.60	
41 REAR BOOT HONDA LOGO	32.7000	1 PC	32.70	
42 REAR BOOT INNER TRIM	292.0000	1 PC	292.00	
43 REAR BOOT INNER TRIM - LH/RH	60.5000	2 PC	121.00	
44 REAR BOOT INNER TRIM TOOLBOX COVER	421.7000	1 PC	421.70	
45 REAR BOOT HINGE - LH/RH	50.0000	2 PC	100.00	
46 REAR BOOT RUBBER	155.5000	1 PC	155.50	
47 REAR BOOT OUTER GARNISH	216.5000	1 PC	216.50	
48 REAR BOOT GLASS MOULDING	231.0000	1 PC	231.00	
49 REAR BOOT OPENER SWITCH	165.0000	1 PC	165.00	
50 REAR BOOT NUMBER PLATE LAMP - LH/RH	42.5000	2 PC	85.00	
51 REAR BOOT INNER COVER - SMALL SIDE - RH	38.0000	1 PC	38.00	
52 REAR FENDER INNER TRIM - LH/RH	809.2000	2 PC	1,618.40	
53 REAR FLOOR PANEL	1,087.400	1 PC	1,087.40	
54 REAR TAILLAMP - LH/RH	897.0000	2 PC	1,794.00	
			23,147.70	
		Less 20%	4,629.54	18,518.16
Special Net				
55 REAR NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	
56 REAR REVERSE CAMERA	350.0000	1 PC	350.00	
57 REAR BUMPER SENSOR (4 PC)	400.0000	1 SET	400.00	
58 REAR FLOOR PANEL SEALANT	350.0000	1 SET	350.00	
59 FRONT NUMBER PLATE WITH CASING	45.0000	1 PC	45.00	
60 COOLANT	50.0000	1 PC	50.00	
ANY				
			1,240.00	1,240.00
Labour				
61 TO KNOCK OUT DENTS, CUT/WELD FRONT PANEL, REAR END PANEL, SPARE TYRE FLOOR PANEL, REMOVE, REPLACE ACCIDENT PARTS	2,200.000	1 JOB	2,200.00	
62 TO RESPRAY PAINT ON ACCIDENT PORTIONS	2,200.000	1 JOB	2,200.00	
63 TO CHECK WIRING	50.0000	1 JOB	50.00	
64 TO REMOVE, REPLACE CONDENSER AND REFILL GAS	100.0000	1 JOB	100.00	
65 TO REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	150.0000	1 JOB	150.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW
 #14-01 ASIA SQUARE TOWER 2
 SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Estimate No: EST1509400

Date: 03 Mar 2023

Policy No: GA610876

Veh Reg No: SLX496J

Make/Model: HONDA ODYSSEY 2.4
 EX-S CVT

Your Ref No: TP 0323-7293

Chassis No: JHMRC1880JC200852

Claim Type: Third Party

Engine No: K24W72400369

Accident Date: 03/03/2023

Reg. Date: 14/03/2018

TP Veh Reg No: SKE 9939 B

Estimate Repair Cost to Vehicle No :SLX496J

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 FRONT BUMPER	831.7000	1 PC	831.70	
2 FRONT BUMPER SIDE HOLDER - LH/RH	24.0000	2 PC	48.00	
3 FRONT BUMPER CLIPS	3.8000	10 PC	38.00	
4 FRONT BUMPER REINFORCEMENT	314.3000	1 PC	314.30	
5 FRONT BUMPER FOG LAMP - LH/RH	284.6000	2 PC	569.20	
6 FRONT BUMPER FOG LAMP COVER - LH/RH	105.0000	2 PC	210.00	
7 FRONT BUMPER LOWER SIDE CHROME MOULDING - LH/RH	120.0000	2 PC	240.00	
8 FRONT BUMPER CENTRE LOWER GRILLE	90.5000	1 PC	90.50	
9 FRONT GRILLE BASE	225.0000	1 PC	225.00	
10 FRONT GRILLE OUTER CHROME	327.0000	1 PC	327.00	
11 FRONT GRILLE OUTER CHROME GARNISH LOGO	27.4000	1 PC	27.40	
12 FRONT GRILLE OUTER CHROME GARNISH LOGO CLIP	4.3000	2 PC	8.60	
13 FRONT GRILLE OUTER CHROME TOP	210.0000	1 PC	210.00	
14 FRONT GRILLE OUTER CHROME CENTER	205.0000	1 PC	205.00	
15 FRONT GRILLE OUTER CHROME LOWER - LH/RH	85.0000	2 PC	170.00	
16 FRONT GRILLE TOP CLIP	4.3000	8 PC	34.40	
17 BONNET	716.6000	1 PC	716.60	
18 BONNET HINGE - LH/RH	50.9000	2 PC	101.80	
19 BONNET INSULATOR	103.7000	1 PC	103.70	
20 BONNET INSULATOR CLIPS	3.9000	10 PC	39.00	
21 BONNET LOCK	135.2000	1 PC	135.20	
22 BONNET RUBBER - LH/RH	29.8000	2 PC	59.60	
23 SUPPORT PANEL	645.0000	1 PC	645.00	
24 AIRCON CONDENSER	764.9000	1 PC	764.90	
25 RADIATOR	1,350.600	1 PC	1,350.60	
26 FRONT HEADLAMP - LH/RH	1,584.000	2 PC	3,168.00	
27 REAR BUMPER	786.9000	1 PC	786.90	
28 REAR BUMPER SIDE HOLDER - LH/RH	23.5000	2 PC	47.00	
29 REAR BUMPER CLIPS	3.8000	10 PC	38.00	
30 REAR BUMPER REFLECTOR - LH/RH	58.6000	2 PC	117.20	
31 REAR BUMPER REFLECTOR CHROME - LH/RH	121.6000	2 PC	243.20	
32 REAR BUMPER CORNER PANEL - LH/RH	98.8000	2 PC	197.60	
33 REAR END PANEL	592.5000	1 PC	592.50	
34 REAR END PANEL TOP GARNISH	150.5000	1 PC	150.50	
35 REAR BOOT	2,490.600	1 PC	2,490.60	
36 REAR BOOT OUTER GARNISH	281.6000	1 PC	281.60	
37 REAR BOOT TOP LOCK	228.6000	1 PC	228.60	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : ALLIANZ INSURANCE SINGAPORE PTE LTD

12 MARINA VIEW

#14-01 ASIA SQUARE TOWER 2

SINGAPORE 018961

TEL: 63958963

ATTN: Motor Claim Department \ ALLIANZ

Your Ref No: TP 0323-7293

Claim Type: Third Party

Accident Date: 03/03/2023

TP Veh Reg No: SKE 9939 B

Estimate No: **EST1509400**

Date: 03 Mar 2023

Policy No: GA610876

Veh Reg No: **SLX496J**

Make/Model: HONDA ODYSSEY 2.4
EX-S CVT

Chassis No: JHMRC1880JC200852

Engine No: K24W72400369

Reg. Date: 14/03/2018

Estimate Repair Cost to Vehicle No :SLX496J

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
66 TO 4 WHEEL ALIGNMENT	80.0000	1 JOB	80.00	
67 TO REMOVE, REFIX REAR EXHAUST	150.0000	1 JOB	150.00	
68 TO TUFF-KOTE	120.0000	1 JOB	120.00	
69 TO REMOVE, REPLACE REAR BUMPER SENSOR	120.0000	1 JOB	120.00	
70 TO REMOVE, REFIT REAR BOOT GLASS	150.0000	1 JOB	150.00	
71 TO RESET CHECKLIGHT	250.0000	1 JOB	250.00	
72 TO REMOVE, TRANSFER REAR BOOT FITTING	100.0000	1 JOB	100.00	
			5,670.00	5,670.00
			Total	S\$ 25,428.16
			Add GST @ 8%	2,034.25
			Total Amount Payable	<u>S\$ 27,462.41</u>

TOTAL: SINGAPORE DOLLAR TWENTY SEVEN THOUSAND FOUR HUNDRED SIXTY TWO AND CENTS FORTY ONE ONLY

For Progressive Car Care Pte Ltd


AUTHORISED SIGNATURE