

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 4TH MARCH 2023

7th March 2023

OWNER : ANG CHWEE BENG

REG. NO. : SLR 7952 U

MAKE/MODEL : KIA NIRO

not Authorised
all
7/3/23
2/5 \$ 2800
4 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(\$)
-----	-------------	------------

LIST ITEMS

1	Rear Tailgate	12	\$	1,289.00	X
1	Rear Tailgate Lock	11	\$	58.50	X
1	Rear Tailgate Logo	11	\$	48.50	X
1	Rear Tailgate Rubber	11	\$	232.60	X
1	Rear Tailgate "NIRO" Emblem	all	\$	48.00	—
1	Rear Tailgate "Hybrid" Emblem	all	\$	43.00	—
1	Rear Tailgate "C&C" Emblem	all	\$	45.00	—
1	Rear End Panel	12	\$	696.50	X
1	Rear End Panel Inner Garnish	11	\$	142.60	X
1	Rear Bumper	De	\$	741.50	—
1	Rear Bumper Inner Sponge	NT	\$	145.00	X
1	Rear Bumper Lower Grille	1W1	\$	525.00	—
2	Rear Bumper Reflectors	W/S 11 015 one	\$	78.00 216.00	120
1	Rear Bumper Reinforcement	one	\$	288 325.00	—
2	Rear Bumper Side Retainers	all	\$	66.00	—
2	Rear Bumper Side Mouldings	one	\$	470.00	—
1	Rear Exhaust Silencer	11	\$	682.50	X
2	Rear Exhaust Moutings	11	\$	65.00	X
				\$	5,839.70
LESS 10%				\$	583.97
				\$	5,255.73

SPECIAL NETT ITEMS

1	Rear Windscreen Sealant	11	\$	80.00	X
1	Rear Bumper Clip (1 Set)	all	\$	60.00	40
1	Rear Bumper Lower Spoiler	2	\$	750.00	X
1	Rear Number Plate with Holder	3001	\$	50.00	40
1	Rear Reverse Sensor (1 Set)	shock	\$	480.00	200

S/N

LABOUR CHARGES

- 1 To remove, replace damaged lamps & check up wiring
- 2 To remove & refit inner garnishes
- 3 To remove & refit rear reverse sensor
- 4 To transfer tailgate mechanism and wiring assembly.
- 5 To apply undercoating
- 6 Panel Beating
- 7 To re-spray the affected areas

\$ 1,420.00

\$	80.00	20
\$	180.00	60
\$	150.00	50
\$	120.00	X
\$	150.00	X
\$	1,400.00	500
\$	1,200.00	600

\$ 3,280.00

\$ 9,955.73

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-23045
112
2074.05
280
1230
5884.05