08/11/13) Wef REF: (S) (TT) 3 (00 2 HHI SVB3
405. REC. 51:	
ASS	IGNMENT
From: Date:	Veh No: GBJ 78795 Yr Regn: 1 2019
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: GBI 7879J	Make: Tuyota Higge c.c 2982
at Werkshop m/s Bifrost	Colour Salver A/C: Insured / Std / NI / NA
	Sp.Reading \\ \frac{1506 \text{ \text{ \ Sp. Readio: Insured / Std / NI / NA}}
of	Eng/No:
insured:	CNO: JTFHTO2P000 · JH9474
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt-or
Sum Insured: Excess:	
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 195 R 15c
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF HABILEAD
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 3 3 3 D.O.I. 8 3 23
Lum Sum: % - 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / (Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	
	4-1-
	×
Date/Time File Page tn?	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation:
Add Fe	
2)	: Interview (\$) Photas
D. A. Francki	: Tech. Invs (\$) Others
Report Format:	:Weekend (\$
Lump Sum / I.B.I: (\$)	TOTAL

wef

(08/11/13)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 825N

Vehicle Details

Vehicle No.: GBJ7879J Vehicle to be Exported: Yes

Intended Deregistration Date: 04 Mar 2023

Vehicle Make: TOYOTA

Vehicle Model: HIACE VAN TURBO 5DR MT

Primary Colour: Silver
Manufacturing Year: 2019

Engine No.: 1KD2868211

Chassis No.: JTFHT02P000249474

Maximum Power Output:

Open Market Value:\$28,138.00Original Registration Date:28 Aug 2019First Registration Date:28 Aug 2019

Transfer Count: 0

Actual ARF Paid: \$1,407.00

Intended PARF Rebate Details

PARF Eligibility: No PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Aug 2029

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

 QP Paid:
 \$24,599.00

 COE Rebate Amount:
 \$15,936.00

 Total Rebate Amount:
 \$15,936.00

The information contained herein is correct as at 04 Mar 2023

Date of Accident	: 03032023 Accident Time: 1820 (24-HR-FORMAT)
Accident Place JALAN AHMAD	IBRAHIM. SLIP ROAD TO JURONG PIER RD
Vehicle Reg. No (Car plate No.)	GBJ 7879J CC: 2982 Vehicle Make/Model: TOYOTA HIACE
Insurance Company	: LONPAL Policy No. 2220 CO 50 1 2712.
Name of Registered Owner	: Company / Individual AZ HITECH PTE LTD.
ID of Registered Owner OWNER EMAIL ADDRESS:	: Co Reg No: 201703825NOwner's NRIC No: -
ALEXLIM & AZHITECH. COM	
DRIVER'S Name	: ARTRAMAN MURUGAN DRIVER'S NRIC No: 67617071N
DRIVER'S Date of Birth	: 0306 1981 DRIVER'S License Pass Date 3004 2013 .
Relationship bet. Owner & Driver	: Spouse Parents Children Call
DRIVER'S Address	: Spouse \ Parents \Children\ Sibling \(Employee\) Others: 35 A GEYLANG LORONG 22.
DRIVER'S Contact No./ Alt No.	:1) \$157 2121. 2)
DRIVER'S Occupation	: INDOOR OUTDOOR (eg. working inside or outside of an ofc)
Email Address	: MURUGAN MNM G GMAIL. COM
Weather & Road Surface	: CLEAR & DRY \ RAINING & WET AFTER RAIN & WET
Reporting Type	Reporting Only Claim Other Part Claim Own Insurance
Number of Passengers (including Dr Was the accident reported to the poli Was there any video Captured by car Exact purpose for which vehicle was Any injuries, if yes(name of the in	camera: YES \NO being used at the time of accident Frivate use) Work purpose
	and Driver & Laffichiare (if any)
Vehicle Reg No: GY 6.7 04,Z	· Chiefe Ven 1/0.
Vehicle Make\Model:	- Vehicle MakelModel:
Name DRIVER:	Name DRIVER
IC No. DRIVER:	
DRIVER'S Contact & add:	
REPORT FORM EXPLAINED IN : ENGLISH	CHINESE / MALAY / TAMIL OTHERS:
WHO REPORTED THE ACCIDENT : OWNER	PRIVER BOTH

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for erchiving and that copies of this report will for a fee be made evaluable upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/iaw firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their tawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



-		7-111									
A	s I	am	trave	lling	on	my	own	lane	at Jo	alan F	HMAD
									s there		
valtin	ng.	to o	cross	af	zębr	ra ci	rossins	IS	top and	d wh	ile
vaiti	ry	for	traff	ic to	clea	-	sudd	enly	top and I fe	lt an	
ingc	. m	pack	from	. ti	ne ro	v of	- my	vehic	le. I	g o f	
ind	gee	, vel	rcle	B	had	hit	onto	my	rear.		
	-							- 1.			
-											
- 100 TUNA											
eclaratio		iolna narii	culars are t	ue in a							-
	ECH A	in		ve in ever	y respect.						

Policyholder's Signature / Dale & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

V

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: GBJ7879J Make & Model: Toyota Hiace

Chassis numbe: JTFHT02P000249474

Date of survey: Name of surveyor:

Contacts:

No.	Description of spare parts	City	Amount S\$		
1	Tailgate 3vt	1	S	2,205.00	
2	Tailgate windscreen glass moulding / CC	1	\$	168.00	
3	Tailgate windscreen glass 13/	1	\$	1,109.00	
4		1	\$	71.60	
5		1	\$	58.00	
			\$	287.00	
7	Tailgate outer handle X	1	\$		
	Tailgate RH number plate lamp X	1	\$	67.00 67.00	
8	Tailgate LH number plate lamp X	1	\$	298.00	
9	Tailgate inner board X				
	Tailgate inner board clips X	1set	\$	80.00	
11	Tailgate central lock actuator	1	\$	485.50	
12	Tailgate central lock actuator mechansim X	1	\$	215.10	
13	Tailgate RH damper X	11	\$	231.00	
	Tailgate LH damper X	1	\$	231.00	
	Tailgate lock 🗸	1	\$	263.00	
_	Tailgate lock catch X	1	\$	40.10	
17	Tailagte inner board cover 🗶	1	\$	444.10	
18	Tailagte inner board cover clips	1set	\$	80.00	
19	Tailgate reverse camera X	1	\$	1,188.18	
20	Tailgate weatherstrip X	1	\$	299.1	
21	Tailgate wiper motor X	1	\$	563.20	
22	Tailgate wiper blade X	1	\$	93.10	
23	Tailgate wiper blade arm X	1	\$	163.00	
24	Rear bumper 3 C	1	\$	706.00	
25	Rear bumper clips MU /	1set	\$	80.00	
26	Rear bumper lower brackets X	4	\$	180.40	
27	Rear bumper RH side bracket 🧚 🖟 🧪	1	\$	32.00	
28	Rear bumper LH side bracket X	1	\$	32.00	
29	Rear bumper RH side retainer 3 /	1	\$	66.10	
30	Rear bumper LH side retainer	1	\$	66.10	
31	RH taillamp assy	1	\$	354.20	
32	RH taillamp lower cover Br	1	\$	78.95	
33	RH taillamp panel	1	\$	231.20	
34	RH taillamp lock clips 🗴	1set	\$	40.00	
35	LH taillamp assy	1	\$	354.20	
36	LH taillamp lower cover X	1	\$	78.95	
37	LH taillamp panel	1	\$	231.20	
38	LH taillamp lock clips ×	1set	\$	40.00	
39	End panel (outer) Park	1	\$	581.80	
40	End panel (inner)	1	\$	1,144.00	
41	End panel RH side rubber stopper 🗸	1	\$	68.10	
42	End panel LH side rubber stopper 💢	1	\$	68.10	
			\$		
43	End panel upper moulding	1	_	198.10	
44	End panel upper moulding RH cover	1	\$	24.10	
45	End panel upper moulding LH cover	1	\$	24.10	

46	End panel RH side panel	1	\$ 315.40
47	End panel LH side panel X	1	\$ 315.40
48	Exhaust silencer	1	\$ 980.20
49	Exhaust silencer gasket	1	\$ 61.10
50	Spare tyre carrier	1	\$ 243.10
51	Spare tyre carrier hook	1	\$ 55.00
			\$ 15.356.83

Parts less 25% \$
Total \$ 3,839.21 11,517.62

No.	Special Nett Items	Qty	An	nount S\$
1	Tailgate windscreen glass sealant	1	\$	80.00
2	Tailgate windscreen glass inner seal	1	\$	60.00
3	Tailgate "70km/h" sticker	1	\$	28.00
4	Tailgate "8pax" sticker	1	\$	28.00
5	Rear bumper reverse sensor	1set	\$	350.00
6	End panel (outer) joint sealant	1	S	80.00
7	End panel (inner) joint sealant	1	\$	80.00
8	Rear number plate	11	\$	70.00
		Total:	S	776.00

No.	Labour and painting		A	mount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and		\$	1,500.00	6 00
	realign all affected panels and areas				
2	Spray painting on affected areas and panels		\$	1,200.00	800
3	Check wiring and lighting system on affected areas		\$	80.00	30
4	Apply rust coating chemical on affected areas and panels		\$	80.00	40
5	Replace tailgate windscreen glass to assist repair		\$	220.00	80
6	Remove and replace tailgate inner mechansim to new tailgate		\$	180.00	60
7	Remove and replace rear bumper reverse sensors to assist repair		\$	100.00	30
8	Remove and replace rear inner board and garnish to assist repair		\$	220.00	40
9	Remove and replace exhaust silencer and gasket to assist repair		\$	180.00	X
		Total:	\$	3,760.00	J

Agreed Amount: _(Part by Part / Lump sum) Working days:

> Spare Parts: \$ 11,517.62 776.00 3,760.00

16,053.62

Spare Parts: \$
Special Nett: \$
Labour: \$

Total Amount: \$

Life \$ 13 | 23 4 30 pm

Spare Parts: \$
Special Nett: \$
\$
Labour: \$

Total Amount: \$

Life \$ 13 | 23 4 30 pm

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875 Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: GBJ7879J Make & Model: Toyota Hiace

rota Hiace

Chassis number:

Date of survey: Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	LH rear side panel pen }	1	\$ 1,638.00

\$ 1,638.00 Parts less 25% \$ 409.50 Total \$ 1,228.50

No.	Special Nett Items	Qty	Amount S\$	7
1	LH rear side panel joint sealant	1	\$ 95,00	4
		Total	\$ 95.00	_

No.	Labour and painting		Aı	mount S\$
1	Labour for supp		\$	1,000.00
2	Spray painting fort supp		\$	1,000.00
	To	otal:	\$	2,000.00

Agreed Amount:_____(Part by Part / Lump sum)
Working days:_____

Spare Parts: \$ 1,228.50 Special Nett: \$ 95.00

Labour: \$ 2,000.00

Total Amount: \$ 3,323.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
 Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: