

Not Authored
C/Imp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7822T

AAD2302-088

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 MAR 2023

SHB7822T

JTDKB3FU103083452

200303878K

TOYOTA

PRIUS

19/02/2023

SJE9888B/TOKIO

30/08/2019

PART

LIST

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 COVER, REAR BUMPER, LOWER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 COVER, FLOOR UNDER, NO.2 (RH)
- 1 COVER, FLOOR UNDER, NO.1 (LH)
- 1 COVER, REAR FLOOR (CTR)
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	558.39	?
\$	726.92	✓
\$	19.43	✓
\$	155.72	?
\$	419.90	?
\$	147.11	X
\$	148.58	X
\$	220.50	X
\$	304.92	X
\$	290.43	X
\$	159.39	X
\$	824.46	X

TOTAL \$ 3,975.72
25% \$ 1,666.03
\$ 4,998.08

Special Nett

- 1 PARKING AID
- 1 REAR LOWER BUMPER CLIP
- 1 REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 1 REAR NUMBER PLATE WITH HOLDER

\$	700.00	X
\$	65.00	60.00
\$	60.00	?
\$	150.00	X
\$	200.00	X
\$	130.00	X
\$	80.00	X
\$	80.00	X
\$	180.00	30.00
\$	140.00	X

TOTAL

\$ 1,785.00

TOTAL PARTS \$ 6,783.08

Trans-cab Auto Services Pte Ltd

AAD2302-088

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7822T

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,400.00	<i>2001</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 480.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,400.00	<i>2201</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>?</i>
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>nn</i> 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>nn</i> 240.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>nn</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	X
TOTAL	\$	5,760.00	
Over All Total	\$	12,543.08	

(PART-BY-PART) Repair Days

*04 days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: