

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Mar 2023)
 Parts: 143 MAZDA 3 1.5 SEDAN AT EUS (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLR8042P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*ROOF PANEL			
2	1		*ROOF MOULDING RH	0.00	0.00	ft ✓ *850.00 F ✓
3	1		*ROOF SIDE PANEL RH	0.00	0.00	de ✓ *50.00 F ✓
4	1		*ROOF LINING	0.00	0.00	buc ✓ *880.00 F ✓
5	1		*REAR BUMPER	0.00	0.00	x ✓ *900.00 F x n n ✓
6	10		*REAR BUMPER CLIPS	0.00	0.00	de ✓ *550.00 F ✓
7	1		*REAR WINDSCREEN GLASS MOULDING	0.00	0.00	net ✓ *40.00 F ✓
8	1		*FRONT WINDSCREEN GLASS MOULDING	0.00	0.00	net ✓ *75.00 F ✓
9	2		*SEALANT	0.00	0.00	net ✓ *65.00 F ✓
				0	0.00	net ✓ *80.00 FS ✓
Sub Total (\$\$)						2510.00 ✓ 3,490.00
+ Margin on L,N Items 10.00% (\$\$)						251.00 341.00
Total Parts (\$\$)						2761.00 ✓ 3,831.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

2841.00 ✓

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: