

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 11 Apr 2023

Preliminary Advice

Vehicle No	: SLR8042P	Accident Date	: 03/03/2023
Make	: MAZDA 3	Policy No.	: SP2002320456
Assignment Date	: 08/03/2023	Excess	: S\$500.00
Date of Inspection	: 10/04/2023	Est. Duration of Repair	: 10
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,831.00
Revised Amount	:S\$	5,401.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,401.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	64,000.00
COE / PARF Rebate	:S\$	27,310.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,690.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :Lump sum repair.
- Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.