

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG23002448/KNY3E2**Date:** 31/03/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001334737

**Claimant Vehicle No :** SMD4741T**Insured Vehicle No :** SLL2789P

Date of Loss: 21/01/2023

Nature of Claim: TP

Claim No: 305744

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMD4741T**

Make &amp; Model: MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)

Engine No: PE21155663

Reg. Date: 21/08/2018 (Man. Year: 2018)

Chassis No: JM6GL1072J0301824

Colour: Metallic Blue

Odometer: 105939 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size: 225/50 R18

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	300.00	100.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>400.00</b>	<b>300.00</b>	<b>100.00</b>	<b>25.00</b>

INSPECTION

Date of Assignment: 09/03/2023

Date Inspected: 27/03/2023 Inspected At:

Tropical Tech Automobile Services (HQ)  
BLK 5032 ANG MO KIO AVENUE 3, #01-303  
INDUSTRIAL PARK 2  
Singapore 569535

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Mar 2023)
Parts:	143	MAZDA 6 2.0 SEDAN EXECUTIVE 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD4741T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING FRONT RH FENDER	New	150.00	100.00
2	PUTTY / PRIMER APPLICATION, SPRAY PAINTING FRONT RH FENDER	New	250.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>400.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >