

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 29 Mar 2023

Preliminary Advice

Insured Vehicle No	: SLL2789P	Accident Date	: 21/01/2023
TP Vehicle No	: SMD4741T	Assignment Date	: 09/03/2023
Make	: MAZDA 6	Est. Duration of Repair	: 2
Date of Inspection	: 27/03/2023		
Inspection At	: TROPICAL TECH AUTOMOBILE SERVICES (HQ) BLK 5032 ANG MO KIO AVENUE 3, #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	400.00
Revised Amount	:S\$	300.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	300.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	89,000.00
COE / PARF Rebate	:S\$	34,926.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,074.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (x) Part-by-Part repair
 () Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.