

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way,
#21-01, SGX Centre Two,

Singapore 068807
Attn : Motor Claims Department
Tel : 6419 3000
Fax : 6225 6772

Estimate bill : TT 13 / 23 / TP / WT

Registration No : SMD4741T

Make / model : Mazda 6

*Not Withheld
Resurvey After Repair
2 days @ 300/-*

Mileage :

Date : 20 / 03 / 2023

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SLL2789P AND SMD4741T ALONG WEST COAST TERRACE ON 21 JANUARY 2023 AT ABOUT 1821HRS.

Panel beating front RH fender.	\$ 100/-	150.00
Putty / primer application, spray painting front RH fender.	\$ 200/-	250.00
Grand final amount :	\$	400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

