

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 22.03.2023
VEH NO : SCW8857K
MODEL : Toyota Crown Royal
D O A : 06.03.2023
YR REF : GBF9168K

Xiao Tony.

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SCW8857K (TOYOTA CROWN ROYAL)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Dented</i>	1	1,955.10 ✓
2	Front Bumper Side Holder - RH <i>2nd</i>	1	79.40 ✗
3	Front Bumper Fog Lamp - RH <i>new</i>	1	349.40 ✗
4	Front Bumper Sensor <i>Dented</i>	1	298.10 ✓
5	Head Lamp - RH <i>cracked</i>	1	2,260.60 ✓
6	Front Fender - RH <i>Dented.</i>	1	863.30 ✓
			5,805.90
Less 25%			(1,451.48)
			\$ 4,354.43

S/NETT ITEMS

1	Front Bumper Clips <i>new</i>	30	1 set	\$ 30.00 ✓
Total Parts				
				\$ 4,384.43

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$ 700.00 <i>500</i>
2	To putty & spray up paint works	\$ 600.00 <i>400</i>
3	To check wiring	\$ 50.00 <i>30</i>
4	To remove front bumper sensor	\$ 100.00 <i>50</i>
Total Labour		
		\$ 1,450.00

Grand Total

\$ 5,834.43

RE : ESTIMATE FOR ACCIDENT REPAIR SCW8857K (TOYOTA CROWN ROYAL)

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 5042.82

4/s: AK.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: