

Not Authorised
Recovery After Pairs
1/1 Day &
7 days

VEHICLE NO: SMQ587E
 CHASSIS NO: ZWR80-0387529

MODEL: TOYOTA NOAH

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>			
REAR BUMPER		\$ <i>1.2</i> 1,600.00	✓
REAR BUMPER RETAINER LHS		\$ <i>1.2</i> 100.00	X
REAR BUMPER RETAINER RHS		\$ <i>1.2</i> 100.00	X
REAR BUMPER TOWING COVER		\$ <i>1.2</i> 50.00	✓
REAR BUMPER CORNER COVER LHS		\$ <i>1.2</i> 180.00	X
REAR BUMPER CORNER COVER RHS		\$ <i>1.2</i> 180.00	X
REAR BUMPER REFLECTOR LHS		\$ <i>1.2</i> 60.00	X
REAR BUMPER REFLECTOR RHS		\$ <i>1.2</i> 60.00	X
REAR TAILGATE		<i>1.2</i> \$ 1,850.00	✓
TAILGATE INNER TRIM		<i>1.2</i> \$ 570.00	X
TAILGATE LOCK ASSY		\$ <i>1.2</i> 480.00	✓
TAILGATE WEATHERSTRIP		<i>1.2</i> \$ 380.00	<i>501.2</i>
TOYOTA EMBLEM		\$ <i>1.2</i> 70.00	✓
HYBRID SYNERGY EMBLEM		\$ <i>1.2</i> 50.00	✓
END PANEL		\$ <i>1.2</i> 750.00	✓
END PANEL GARNISH		<i>1.2</i> \$ 160.00	✓
FLOORBOARD		<i>1.2</i> \$ 1,120.00	X
TAIL LAMP LHS		\$ <i>1.2</i> 680.00	X
TAIL LAMP RHS		\$ <i>1.2</i> 680.00	X
REAR FENDER RHS		\$ <i>1.2</i> 1,350.00	X
REAR FENDER LHS		\$ <i>1.2</i> 1,350.00	X
REAR WINDSCREEN MOULDING		\$ <i>1.2</i> 120.00	✓
REAR FENDER INNER TRIM LHS		<i>1.2</i> \$ 600.00	✓
REAR FENDER INNER TRIM RHS		<i>1.2</i> \$ 600.00	✓
BATTERY BRACKET		\$ <i>1.2</i> 230.00	X
SPARE TYRE PANEL		\$ <i>1.2</i> 700.00	X
SPARE TYRE PANEL TOP COVER		<i>1.2</i> \$ 1,110.00	✓
		\$ 15,180.00	
25%		\$ 3,795.00	
		\$ 11,385.00	

SPECIAL NETT ITEMS

REAR BUMPER CLIPS 1 SET

REAR SENSORS

\$ *12* 60.00

\$ *100* 200.00

Total

\$ 260.00

TOTAL PARTS

\$ 11,645.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,800.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,800.00	1000
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20
4	To provide anti-rust treatment on affected areas	\$ 100.00	60
5	Transfer tailgate parts	\$ 150.00	60
6	Remove & refit rear windscreen	\$ 150.00	120
7	Remove & refit rear sensors	\$ 100.00	50
8	Remove & refit rear upholstery	\$ 200.00	100
	Labour Total :	\$ 4,200.00	
	TOTAL (PARTS & LABOUR):	\$ 15,845.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: