

Vehicle Damage Assessment Report for [SBD8508E]

Estimate Created: 19/04/2023 14:55 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 19/04/2023 15:03 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	SG1211361
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pt e_Ltd	Reference Number	

Vehicle Information

Brand	Mitsubishi	Model	Attrage
Engine Type			
License Plate Number	SBD8508E	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$2,000.00 WITH 3 WORKING
DAYS

Insurlogic 4 (19/04/2023 15:03)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Bootlid Logo badge		1	41.00	-10.00 %	36.90
Bootlid emblem Attridge		1	38.00	-10.00 %	34.20
Bootlid emblem MIVEC		1	85.00	-10.00 %	76.50
Rear bumper		1	708.00	-10.00 %	637.20
Rear bumper side retainer RH		1	28.00	-10.00 %	25.20

Parts Subtotal 810.00

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear bumper lower skirt		1.0	800.00	0.00 %	800.00
Rear bumper clips		1.0	30.00	0.00 %	30.00
Bootlid emblem "CC"		1.0	30.00	0.00 %	30.00
Rear bumper lower skirt clips		1.0	30.00	0.00 %	30.00

Materials Subtotal 890.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	300.00	0.00 %	300.00
To remove and replace rear reverse sensor	RnR	40.00	0.00 %	40.00

Repair

Description	Severity	Cost	Markup/Disc %	Price
Bootlid	Medium	0.00	0.00 %	0.00
Rear end panel	Medium	0.00	0.00 %	0.00
Rear fender RH	Medium	0.00	0.00 %	0.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	500.00	0.00 %	500.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 340.00

Paint Labor Subtotal 500.00

Labor Subtotal 840.00

Summary

Repair Cost	2,540.00
Discount(20 %)	(508.00)
	2,032.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	2,032.00
