Estimate

			L	sumate					
	KK AUTO CONSULTANTS PTE LI	Profor	ma Ir	nvoice No:	Date: Apr 25 2023				
Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com					No:	LKK-J000	Vehicle No: SLV4381R		
					No:	51225480	Claim No: 0		
A C R P	ompany Name: INDIA INTERNATIONA ddress: 64 Cecil Street,#04-02 IOB Build ity: Singapore egion: Central Singapore ostal Code: 049711 o.Reg.No: 198703792K		ANCE		: BMV ter: 0 WHIT ETRO	E L		ACK 116d 2017	
#	Part Name	Description	on Quantity	Unit Price	Paya	ble Amount	Discount	Taxable	Parts Total
1	ROCKER PANEL SPOILER LH	Part	1.00	593.80	·	415.66	178.14	415.66	415.66
2	ROCKER PANEL SPOILER RETAINER (REAR)	Part	1.00	195.10		136.57	58.53	136.57	136.57
3	SPORT RIM ASSY (REAR LH)	Part	1.00	600.00		420.00	180.00	420.00	420.00
								Taxable Value Discount Total Grand Total	972.23 416.67 972.23
						1	1		
#	Service		Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
4	TO RESPRAY AFFECTED AREAS		Labour	-	800.00	800.00	0.00	800.00	800.00
5	FO RENEW DAMAGED PARTS STRAIGHTEN & REPAIR REAR BUMPER ,REAR LH DOOR ,REAR LH FENDER FRONT LH DOOR & ALIGNED ALL PARTS		Labour	-	420.00	267.77	152.23	267.77	267.77
6	TO REMOVE & REFIX REAR LH SPORT RIM & WHEEL BALANCING	Labour	-	60.00	60.00	0.00	60.00	60.00	
								Taxable Value	1,127.77
								Discount Tota	1 152.23
								Grand Total	1,127.77
						Parts Total 972.23			
						Labour Tot	al		1,127.77
						GST Total			0.00
						Grand Tota	ıl		2,100.00
						Balance			2,100.00
	ertify that the work has been done ndition, with all items / valuables			and that I	have	taken deli	very of the	he vehicle in g	good

Cashier / Authorized Signature

Customer / Authorized Signatory Service Advisor Signature