

(08/11/13) wof

ASS. REC. BY: AME

REF:

CS/EH123002461/R y3

7914

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNA 7281Mat Workshop m/s VOLKSWAGENof ALEXANDRA RDInsured: EG1

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 125K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 7281M Yr Regn: 2021 JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: SKODA SCALA / SM-CTS / SR C.C. 1498Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 34694 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TMBFK6NW0M3126688Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45R18

R: _____

BS / DUN / EXNOVA / GY-PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/03/23Survey held at Volkswagen

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 10/03/23

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/D

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 73K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$I

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

ŠKODA Centre Singapore

26 Leng Kee Rd

Singapore 159104

Biz. Reg. No.: 199101494Z

GST No.: M200985052



SKODA

Commercial Vehicles

Surveg = 10/3/2023 @
12 pm (Rasul)

Quotation

Non binding - Preview

Page

1/2

Company

ERGO INSURANCE PTE. LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
Singapore 038988

Customer Details:

Mr
Toong
Seng Ern
BLK 792 YISHUN RING ROAD
#09-3442
SINGAPORE 760792

Document no.

Document date 07-03-2023
Customer no. 5211001034
Customer GST-ID 199305211H
Dealer 30001
Job order number 2023006435/ 1
Job order date 07-03-2023
Service Advisor Hui Wen Oh

License plate	Model code	First registration	VIN	Model	Mileage
SNA7281M	NW17KDM1	09-07-2021	TMBFK6NW0M3126688	Scala Monte Carlo 1.5 TSI 110kW DSG EVO	29,955

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES REPAIR				#6	280.00	302.40
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#6	480.00	518.40
9801B001	CHANGE LANE ASSIST SYSTEM CALIBRATION				#6	840.00	907.20
657853687E 041	Unbekannt	1	pcs.	95.63	#6	95.63	103.28
657807417	Stoßfänger REAR BUMPER	1	pcs.	1,656.46	#6	1,656.46	1,788.98
657919485C	Geberhalter SENSOR BRACKET	1	pcs.	14.14	#6	14.14	15.27
657919485B	Geberhalter	1	pcs.	14.14	#6	14.14	15.27
657919486B	Geberhalter	1	pcs.	14.14	#6	14.14	15.27
657919486C	Geberhalter	1	pcs.	14.14	#6	14.14	15.27
5Q0919275B GRU	Sensor Primed	1	pcs.	194.63	#6	194.63	210.20
5Q0919133 9B9	Seal Ring Satin Black	1	pcs.	1.53	#6	1.53	1.65
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	84.64	#6	84.64	91.41
D 822150A1	Bonding Agent For Plastic	1	pcs.	74.37	#6	74.37	80.32
657807521B	Unbekannt BUMPER SPOILER	1	pcs.	260.15	#6	260.15	280.96
657807251	Schaumstoffrohr REINFORCEMENT	1	pcs.	118.39	#6	118.39	127.86
657807863A	Unbekannt BUMPER CTR BRACKET	1	pcs.	72.05	#6	72.05	77.81
657807394	RHS Guide Profile RHR BUMPER BRACKET (UPPER)	1	pcs.	41.04	#6	41.04	44.32
657807393	LHS Guide Profile LHR BUMPER BRACKET (UPPER)	1	pcs.	41.04	#6	41.04	44.32
657807393A	LHS Guide Profile LHR BUMPER BRACKET (SIDE)	1	pcs.	52.45	#6	52.45	56.65
657807394A	RHS Guide Profile RHR BUMPER BRACKET (SIDE)	1	pcs.	49.54	#6	49.54	53.50
657945207	Led-Schlussleuchte LHR TAILLIGHT OUTER	1	pcs.	898.49	#6	898.49	970.37
657945701A	Rückstrahler LHS REFLECTOR	1	pcs.	49.03	#6	49.03	52.95
2Q0907685B	Control Unit For Blind Sp BLIND SPOT CONTROL UNIT LH	1	pcs.	1,033.22	#6	1,033.22	1,115.88
657907455	Halter BLIND SPOT CONTROL UNIT BRACKET LH	1	pcs.	19.51	#6	19.51	21.07
657810969	Wheelhouse LHR FENDER LINER	1	pcs.	223.69	#6	223.69	241.59

ŠKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
ERGO INSURANCE PTE. LTD
8 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER THREE
Singapore 038988

Customer Details:
Mr
Toong
Seng Ern
BLK 792 YISHUN RING ROAD
#09-3442
SINGAPORE 760792

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

07-03-2023
5211001034
199305211H
30001
2023006435/ 1
07-03-2023
Hui Wen Oh

License plate	Model code	First registration	VIN	Model	Mileage
SNA7281M	NW17KDM1	09-07-2021	TMBFK6NW0M3126688	Scala Monte Carlo 1.5 TSI 110kW DSG EVO	29,955

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	DESCRIPTION: HL ANY WS VS ERGO DIRECT DOA: 6/3/2023 TP VEH NO: SNJ791G SURVEY BY: LABOUR	5	pcs.	840.00	#6	4,200.00	4,536.00
	SPRAY PAINT	5	pcs.	800.00	#6	4,000.00	4,320.00

Quotation valid till 14-03-2023

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#6	1,600.00	13,222.42	8%	1,185.79	14,822.42	16,008.21
Total	1,600.00	13,222.42		1,185.79	14,822.42	16,008.21

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer

Acknowledged by Repairer

Signature:

Date:

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).

All invoices are denominated in SGD, unless otherwise stated.

Handwritten notes:
Rahul
Hp 90010068
3 days
10/03/23 @ 1205
Resurvey before paint

Service Advisor

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 791H

Vehicle Details

Vehicle No.: SNA7281M

Vehicle to be Exported: No

Intended Deregistration Date: 12 Mar 2023

Vehicle Make: SKODA

Vehicle Model: SCALA 1.5 MONTE CARLO TSI

Primary Colour: White

Manufacturing Year: 2021

Engine No.: DPC191028

Chassis No.: TMBFK6NW0M3126688

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$22,831.00

Original Registration Date: 09 Jul 2021

First Registration Date: 09 Jul 2021

Transfer Count: 1

Actual ARF Paid: \$8,964.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 08 Jul 2031

PARF Rebate Amount: \$6,723.00

Intended COE Rebate Details

COE Expiry Date: 08 Jul 2031

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$58,089.00

COE Rebate Amount: \$48,338.00

Total Rebate Amount: \$55,061.00

Skoda Scala 1.5A TSI Monte Carlo

Overview

Insurance

Financial

Accessories

Similar

Research

Photos

Price

\$125,800

Depreciation ⓘ

\$14,060 /yr

[View models with similar depre](#)

Reg Date

12-Mar-2021

(7yrs 11mths 27days COE left)

Mileage

27,943 km (14k /yr)

Manufactured ⓘ

2020

Road Tax ⓘ

\$684 /yr

Transmission

Auto

Dereg Value ⓘ

\$59,917 as of today ([change](#))

OMV ⓘ

\$24,638

COE ⓘ

\$51,900

ARF ⓘ

\$26,494

Engine Cap

1,498 cc

Power

110.0 kW (147 bhp)

Curb Weight ⓘ

1,260 kg

No. of Owners ⓘ

2

Type of Vehicle

[Hatchback](#)