

(08/15/13) wsf

ASS. REC. BY: PMUREF: CS/CT12300 2462/R up 3

0929

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_


OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMV 33984at Workshop m/s PERFORMANCEof BUENAVISTA RDInsured: SMV 7677G CTIPolicy No. DMPCSNW00249082200Claims No. SNM23D201749/C02/LEEPG

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 213K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMV 33984 Yr Regn: 2021 / F6BType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 520I LUX ADAPLED / 1998Colour: BLACK A/C: insured / Std / NI / NASp. Reading: 37510 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA72A40W X07919Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/03/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT / 121K

26/6/23 Final fig \$7241.10 confirmed by email (red 2339.55, 24%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 26/6/23-typist

Days Of Repair: 5

Resurvey No. of Trip: \_\_\_\_\_

Report Format: Merimen

Lump Sum / I.B.I: (\$ 7241.10 )

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	07/03/2023 14:31 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	06/03/2023 18:48 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TANJONG RHU
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMY3398Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	YEOH PHAIK HONG
NRIC No	SXXXX092G
Email Address	patrick.yeoh@yahoo.com
Mobile Phone No	(Phone) +65-97829789
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	BMW
Model	520i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

#### INSURANCE COMPANY

Name of Insurance Company	Etika Insurance Pte Ltd
Policy Number / Cover Note Number	M0039210

#### DRIVER

Name of Driver	YEOH PHAIK HONG
NRIC No	SXXXX092G
Date Of Birth	15/12/1960
Occupation	Indoor



Date Of Driving Pass	19/03/1992
Driving experience	31 YEARS
Gender	Male
Mobile Number	(Phone) +65-97829789
Alt. Phone Number	-
Email Address	patrick.yeoh@yahoo.com
Address	19B HILLVIEW AVENUE #10-07
Address complement	-
Postcode	669555
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACH

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMV7677G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MR ONG
Contact Number	(Phone) +65-96911997

Address	-
Address complement	-
Postcode	-
Insurance Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage	FRONT
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

## SKETCH PLAN




## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stopped at the Tanjung Rhu traffic light and the car didn't brake and hit the rear bumper of my car.

Location: in front of WaterSide Condominium junction


## DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature

Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

7/3/2023


09426


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 65233  
Date Estimated : 07/03/2023  
Prepared By : Chua Kee Sin

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Yeoh Phaik Hong  
19B Hillview Avenue  
#10-07

Singapore 669555

## - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMY3398Y	WBA72AG090WX07919	09/02/2021	520i Sedan	29659

## DESCRIPTION

Replace rear bumper include remove attachment etc included repair  
rear boot  
lid

Painting rear bumper and rear boot lid

To check electrical wiring system and lighting at the  
rear section for proper function.

To remove old PDC assembly, replace damaged parts and  
reconnect to new bumper including conduct check for  
proper function.

Sundries.

1700 1275 1200 VALUE  
2,125.00

1972 2,076.00

168 177.00

168 177.00

80 ? 150.00

Total Labour 1: 4,705.00

## DESCRIPTION

LEFT PROTECTION FOIL ? Xan

RIGHT PROTEC ? Xan

REAR BUMPER CARRIER ? bt

REAR BUMPER TRIM STRIP (LUXURY) cut

REAR BUMPER BOTTOM TRIM PANEL see

REAR CENTRE GUIDE ? cm

REAR BUMPER BOTTOM REINFORCEMENT ? bt

REAR TOWING EYE COVER PRIMED Xan

REAR BUMPER TRIM PANEL (PDC/PMA) de

SET MOUNTING PDA/PMA SENSOR REAR ? Xan

DECOUPLING RING see Xan

ULTRASONIC SENSOR SOPHISTO GREY ? Xan

QTY	PRIC	VALUE
1	14.15	14.15
1	14.15	14.15
1	608.95	608.95
1	159.60	159.60
1	317.05	317.05
1	179.90	179.90
1	171.90	171.90
1	55.30	55.30
1	1,664.50	1,664.50
1	73.75	73.75
4	5.30	21.20
4	386.00	1,544.00

Total Parts : 4,824.45

## Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 65233  
Date Estimated : 07/03/2023  
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMY3398Y	WBA72AG090WX07919	09/02/2021	520i Sedan	29659

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct &  
Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date&Time 21/03/23 @ 1530 Excess S\$ \_\_\_\_\_  
Surveyor's Name Pasul Sign \_\_\_\_\_  
Surveyor's Tel 90016068 Authorised Y  
Authorised Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P  
Surveyor's E-mail \_\_\_\_\_  
Working Days Recommend 5 days



Labour 1	:	4,705.00
Parts	:	4,824.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 8%	:	762.36
Grand Total	:	<u>10,291.81</u>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY \*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



# Performance Motors

BMW Dealer



## Final Report

Estimate No. : b1 65233  
Date Estimated : 07/03/2023  
Prepared By : Chua Kee Sin

Page No. :

**- ESTIMATE REPAIR FOR -**

Yeoh Phaik Hong  
19B Hillview Avenue  
#10-07

Singapore 669555

**- ACCOUNT - 135**

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMY3398Y	WBA72AG090WX07919	09/02/2021	520i Sedan	38660

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
** To replace rear bumper panel, rear underbody panelling, rear bottom reinforcement, rear centre guide, rear bottom trim panel, rear trim strip, rear carrier include making good the boot lid and carrying out necessary repairs caused by the accident	1,700.00		1,700.00
To spray paint rear bumper and boot lid	1,972.00		1,972.00
To check electrical wiring system and lightings at the rear section for proper function	168.00		168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00		168.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	608.95	1.00	0.00	608.95
REAR BUMPER TRIM STRIP (LUXURY)	159.60	1.00	0.00	159.60
REAR BUMPER BOTTOM TRIM PANEL	317.05	1.00	0.00	317.05
REAR CENTRE GUIDE	179.90	1.00	0.00	179.90
REAR BUMPER BOTTOM REINFORCEMENT	171.90	1.00	0.00	171.90
REAR BUMPER TRIM PANEL (PDC/PMA)	1,664.50	1.00	0.00	1,664.50
# UNDERBODY PANELLING REAR	51.20	1.00	0.00	51.20

**# SUPPLEMENTARY ITEMS**

Total Labour :	4,088.00
Total Parts :	3,153.10
Total Labour & Parts (before GST) :	7,241.10
Deduction for Excess :	
Total Repair Costs less Excess:	7,241.10
GST @8%:	579.29
Grand Total :	7,820.39

Performance Motors Limited.  
Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

A Sime Darby Motors Company

# Performance Motors

BMW Dealer



## Supplementary

Estimate No. : b1 65233  
Date Estimated : 07/03/2023  
Prepared By : Chua Kee Sin

Page No. :

### - ESTIMATE REPAIR FOR -

Yeoh Phaik Hong  
19B Hillview Avenue  
#10-07

Singapore 669555

### - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMY3398Y	WBA72AG090WX07919	09/02/2021	520i Sedan	38660

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

** To replace rear bumper panel, rear underbody panelling, rear bottom reinforcement, rear centre guide, rear bottom trim panel, rear trim strip, rear carrier include making good the boot lid and carrying out necessary repairs caused by the accident	1,700.00		1,700.00
---	----------	--	----------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# UNDERBODY PANELLING REAR <i>Ch</i>	51.20	1.00	0.00	51.20
--------------------------------------	-------	------	------	-------

### # SUPPLEMENTARY ITEMS

Total Labour :	1,700.00
Total Parts :	51.20
Total Labour & Parts (before GST) :	1,751.20

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W

A Motors Company