

MBM WHEELPOWER PTE. LTD.

YOUR REF.:

OUR REF.: SLA9724M

TO: INDIA INTERNATIONAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

ESTIMATE FOR VEHICLE NO.: SLA9724M

DATE: 7/3/2023
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA HARRIER 2.0 PREMIUM
CHASSIS NO.: ZSU600073557
ENGINE NO.: 3ZRB738573
YEAR MADE: 2016
ACCIDENT DATE: 4 March 2023

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 900.00
2	BONNET INSULATOR		1	\$ 450.00
3	BONNET SEAL RH		1	\$ 90.00
4	BONNET HINGE RH		1	\$ 90.00
5	BONNET SUPPORT RH		1	\$ 380.00
6	BONNET MOULDING		1	\$ 270.00
7	FRONT RADIATOR GRILLE		1	\$ 450.00
8	FRONT BUMPER		1	\$ 450.00
9	FRONT BUMPER OUTER SIDE RETAINER RH		1	\$ 90.00
10	FRONT BUMPER INNER SIDE RETAINER RH		1	\$ 90.00
11	FRONT BUMPER ABSORBER RH		1	\$ 120.00
12	FRONT BUMPER REINFORCEMENT		1	\$ 360.00
13	FRONT BUMPER LOWER ABSORBER		1	\$ 270.00
14	FRONT BUMPER ABSORBER		1	\$ 135.00
15	FRONT BUMPER LOWER GRILLE		1	\$ 210.00
16	FRONT BUMPER FOG LAMP COVER RH		1	\$ 110.00
17	FRONT BUMPER GUIDE		1	\$ 120.00
18	FRONT BUMPER TOWING COVER RH		1	\$ 50.00
19	FRONT BUMPER CLIP		10	\$ 30.00
20	HEADLAMP RH		1	\$ 2,050.00
21	FOG LAMP RH		1	\$ 210.00
22	FRONT FENDER RH		1	\$ 320.00
23	FRONT FENDER PROTECTOR RH		1	\$ 150.00
24	FRONT FENDER INNER SHIELD RH		1	\$ 320.00
25	FRONT FENDER INNER SHIELD CLIP		10	\$ 30.00
26	FRONT SUPPORT PANEL		1	\$ 650.00
27	FRONT WHEEL HOUSE RH		1	\$ 630.00



28	APRON SUB-ASSY, FRONT FENDER, RH	1	\$	630.00
29	FRONT PILLAR COVER RH	1	\$	150.00
TOTAL:				\$ 9,655.00
LESS 25%:				\$ (2,413.75)
PARTS TOTAL:				\$ 7,241.25

SPECIAL NETT

NUMBER PLATE & HOLDER	1	\$	50.00
BODY SEALANT	1	\$	50.00
FIRELLI TYRE 235/50 R19	1	\$	320.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	1,800.00
TO CONDUCT CHASSIS ALIGNMENT	\$	250.00
TO REMOVE,RENEW & REFIT FRONT RH TYRE	\$	80.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	160.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	200.00
TO REMOVE & REFIT ALL SENSOR	\$	250.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	250.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	1,200.00
TOTAL:	\$	11,851.25
7% GST:	\$	829.59
GRAND TOTAL:	\$	12,680.84