

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Priya

Date: 16 Mar 2023

Preliminary Advice

Vehicle No	: SLA9724M	Accident Date	: 04/03/2023
Make	: TOYOTA HARRIER	Policy No.	: D20MPC0001414_02
Assignment Date	: 08/03/2023	Excess	: S\$0.00
Date of Inspection	: 08/03/2023	Est. Duration of Repair	: 07 days
Inspection At	: MBM WHEELPOWER PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,147.70	(Est \$11,851.20 + Supp \$2,296.50)
Revised Amount	:S\$	9,643.00	(Inclu. \$2,296.50)
Check Items (Estimated)	:S\$	2,531.25	
Total	:S\$	12,174.25	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	31,767.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,233.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on Supplementary Items.