

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sundari Nagarajan

Date: 09 Mar 2023

**Preliminary Advice**

Vehicle No	: SLA9724M	Accident Date	: 04/03/2023
Make	: TOYOTA HARRIER	Policy No.	: D20MPC0001414_02
Assignment Date	: 08/03/2023	Excess	: S\$0.00
Date of Inspection	: 08/03/2023	Est. Duration of Repair	: 07 DAYS
Inspection At	: MBM WHEELPOWER PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,851.20
Revised Amount	:S\$	7,346.50
Check Items (Estimated)	:S\$	2,531.25
Total	:S\$	9,877.75

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	31,767.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,233.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.