

MBM WHEELPOWER PTE. LTD.

YOUR REF.:

OUR REF.: SLA9724M

TO: INDIA INTERNATIONAL

CC: MOTOR CLAIMS DEPARTMENT

FAX:

SUPPLEMENTARY FOR VEHICLE NO.: SLA9724M



DATE: 16/3/2023
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA HARRIER 2.0 PREMIUM
CHASSIS NO.: ZSU600073557
ENGINE NO.: 3ZRB738573
YEAR MADE: 2016
ACCIDENT DATE: 4 March 2023

Not looked

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	FRONT SUPPORT SUB-ASSY, RADIATOR, RH		1	\$ <i>B1</i> — 135.00
2	FRONT RADIATOR SIDE AIR GUIDE PLATE REAR RH		1	\$ <i>CM</i> — 90.00
3	FRONT FAN COWLING TOP COVER		1	\$ <i>CM</i> — 140.00
4	FRONT FENDER GARNISH RH		1	\$ <i>CM</i> — 95.00
5	FRONT SUPPORT PANEL TOP GARNISH		1	\$ <i>h1</i> — 350.00
6	FRONT SUPPORT PANEL TOP GARNISH CLIP		5	\$ <i>h1</i> — 30.00
7	FRONT RADIATOR SPARE TANK		1	\$ <i>CM</i> — 270.00
8	FRONT RESONATOR, INTAKE AIR TANK <i>wipe tank</i>		1	\$ <i>h1</i> — 338.00 ✓
9	FRONT FENDER TO COWL SIDE SEAL RH		1	\$ <i>B1</i> — 115.00 ✓
10	FRONT COOLER PIPE <i>R1</i>		1	\$ <i>B1</i> — 770.00 ✓
11	FRONT SHIELD SUB-ASSY FENDER SPLASH REAR RH		1	\$ <i>CM</i> — 160.00 ✓
12	FRONT BUMPER UPPER REINFORCEMENT		1	\$ <i>h1</i> — 385.00 ✓
13	FRONT BUMPER PIN HOLD CLIP	4774950090	2	\$ <i>h1</i> — 24.00
14	FRONT FENDER INNER SHIELD RETAINER	5387930050	2	\$ <i>h1</i> — 50.00
15	FRONT FENDER BRACKET LH		1	\$ <i>B1</i> — 110.00
TOTAL:				\$ 3,062.00
LESS 25%:				(765.50)
PARTS TOTAL:				\$ 2,296.50
TOTAL:				\$ 2,296.50
8% GST:				\$ 183.72
GRAND TOTAL:				\$ 2,480.22

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W