



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002470/Awy3e2 Date: 26/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 10G	Veh. Inspected	SJJ 7934M
Policy No.		Coverage (\$)	0.00
Claim No.	D23000820MFBP	Excess (\$)	0.00
Assign From	AINI BINTE	Assign Date	08/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053BK4107033260	Colour	BLACK
Odometer	220440 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/50 R16	HANKOOK	6 mm
L/H Front Tyre	205/50 R16	HANKOOK	6 mm
R/H Rear Tyre	205/50 R16	HANKOOK	6 mm
L/H Rear Tyre	205/50 R16	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/03/2023	Inspection Date	09/03/2023
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	