

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C

GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 08/03/2023

08/03/2023

Estimated repair cost for vehicle no: SJJ7934M TOYOTA CAMRY 2.0 AUTO ABS AIRBAG
CHASSIS: MR053BK4107033260 (2008)

S/N	Qty	Items	U/price	Amount
1	1	REAR BOOTLID <i>Dented</i>	\$1,374.20	\$1,374.20 1086
2	1	REAR BOOTLID LOCK <i>Dented</i>	\$349	\$349 1
3	1	REAR BOOTLID LOCK DETECTOR <i>New</i>	\$183.60	\$183.60 <i>x</i>
4	2	REAR BOOTLID NUMBER PLATE LAMP <i>Replaced</i>	\$55.20	\$110.40 <i>2</i>
5	1	REAR BOOTLID CHROME MOULDING <i>Cracked</i>	\$354.20	\$354.20 <i>✓</i>
6	2	REAR BOOTLID HINGE GARNISH <i>New</i>	\$164.20	\$328.40 <i>x</i>
7	1	REAR BOOTLID INNER TRIM <i>New</i>	\$365.70	\$365.70 <i>x</i>
8	2	REAR BOOTLID LAMP <i>Cracked</i>	\$640.30	\$1,280.60 963
9	1	REAR BUMPER <i>Dented</i>	\$745.30	\$745.30 685
10	1	REAR BUMPER REINFORCEMENT <i>Dented</i>	\$512.30	\$512.30 420
11	2	REAR BUMPER SIDE RETAINER <i>New</i>	\$114.80	\$229.60 <i>x</i>
12	1	REAR WEATHER STRIPE <i>Cracked</i>	\$311	\$311 <i>2</i>
13	1	REAR END PANEL <i>Dented</i>	\$698.60	\$698.60 <i>✓</i>
14	1	REAR END PANEL TOP GARNISH <i>Dented</i>	\$324.30	\$324.30 <i>✓</i>
15	1	REAR KEYLESS SENSOR <i>New</i>	\$164.50	\$164.50 <i>x</i>
16	1	REAR KEYLESS SENSOR WIRE HARNESS <i>New</i>	\$283.60	\$283.60 <i>x</i>
17	1	REAR KEYLESS BUZZER <i>New</i>	\$184.50	\$184.50 <i>x</i>
18	2	REAR TAILLAMP <i>Replaced</i>	\$845.10	\$1,690.20 1090
19	2	REAR TAILLAMP LOWER BRACKET <i>New</i>	\$125.70	\$251.40 <i>x</i>

Bootlid outer garnish *✓*

Cracked

6391.50

4793.62

TOTAL : \$9,473.20
LESS 25 % \$2,368.30
SUB-TOTAL : \$7,104.90

SJJ7934M TOYOTA CAMRY

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR REVERSE CAMERA <i>Engd</i>	\$ 800.00	\$ 800.00 <i>380</i>
2	1	REAR BUMPER CLIPS <i>Ne</i>	\$ 80.00	\$ 80.00 <i>30</i>
3	1	REAR NUMBER PLATE WITH CASING <i>Ne</i>	\$ 60.00	\$ 60.00 <i>x</i>
4	1	REAR FENDER INNER TRIM BOARD CLIPS <i>Ne</i>	\$ 40.00	\$ 40.00 <i>+</i>
5	1	REAR END PANEL CLIPS <i>Ne</i>	\$ 50.00	\$ 50.00 <i>20</i>
6	2	REAR BOOTLID HINGE GARNISH CLIPS <i>Ne</i>	\$ 30.00	\$ 30.00 <i>+</i>
7	1	REAR END PANEL SEALANT <i>Ne</i>	\$ 100.00	\$ 100.00 <i>60</i>
8	1	Reverse sensor <i>Engd</i>	<i>280</i>	<i>200</i>
TOTAL:				\$1,160.00
TOTAL PARTS:				\$8,264.90

Labour charges

1	LABOUR FOR PANEL BEATING	2010	\$2,000.00 <i>820</i>
2	LABOUR FOR SPRAYPAINTING	2030	\$1,500.00 <i>90</i>
3	LABOUR FOR REMOVE / RENEW & TRANSFER REAR BOOTLID FITTING		\$250.00 <i>60</i>
4	WIRING CHECK		\$80.00 <i>30</i>
5	TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS		\$300.00 <i>60</i>
6	Labour to remove upholstery	<i>150</i>	<i>60</i>
7	Labour to remove reverse sensor	<i>120</i>	<i>50</i>
8	Labour to remove rear camera	<i>120</i>	<i>50</i>
Subtotal :-			\$4,130.00
Total:-			\$12,394.90

Admin *L*
 H/c 09/03/23.

no of days . 06 Days .

total: 7493.62
 L/S. 6K.

6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: