

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : PD3993D
VEHICLE MODEL : VOLVO B8R
CHASSIS NO : YV3T7U527NA209331

TP China.
Fzlyng.

CLAIM DETAILS: PARTS

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Distorted</i>	1	\$ 3,500.00	\$ 3,500.00
2	HEADLAMP <i>new</i>	1	\$ 3,000.00	\$ 3,000.00
3	FRONT RH COMPARTMENT COVER <i>Buckled</i>	1	\$ 1,200.00	\$ 1,200.00
4	FRONT COMPARTMENT COVER LOCK <i>new</i>	1	\$ 250.00	\$ 250.00
5	FRONT COMPARTMENT COVER LOCK HANDLE <i>new</i>	1	\$ 100.00	\$ 100.00
6	FRONT RH COMPARTMENT COVER LOWER PANEL <i>repair</i>	1	\$ 800.00	\$ 800.00

TOTAL : \$ 8,850.00

3600.

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,500.00	700	
2	SPRAY PAINTING TO AFFECTED AREA (MULTI COLOURS)	\$ 1,200.00	600	
3	WIRING CHECK	\$ 150.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	80	

TOTAL: \$ 3,000.00

1310

ESTIMATE REPORT

TOTAL PARTS COST: \$ 8,850.00
TOTAL LABOUR COST: \$ 3,000.00
TOTAL REPAIR COST: \$ 11,850.00

total 5110
L/S: A-1K

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FAX:

04 Days

A-1K