

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI23002488/AQY3M4**Date:** 16/03/2023**REFERENCE**

Insured/Claimant: NAPOLIZZ PIZZA PTE LTD Policy No: DMPCSNW00158392200

Date of Loss: 28/02/2023

Nature of Claim: OD

Claim No: SNM23D201637/C01/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMT5825U**

Make &amp; Model: FORD MUSTANG, 5.0 GT (A)

Engine No: J5141003

Reg. Date: 02/07/2020 (Man. Year: 2018)

Chassis No: 1FA6P8NF2J5141003

Colour: Orange

Odometer: 0 km

Engine Capacity: 5038 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 255/40 R19

Rear Tyre Size: 255/40 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (\$\$)</b>	5,000.00	5,000.00	0.00	0.00
<b>Nett Amount (\$\$)</b>	<b>-5,000.00</b>	<b>-5,000.00</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 10/03/2023

Date Inspected: 09/03/2023 Inspected At:

Xin Yun Auto Pte Ltd (kaki Bukit) (HQ)  
8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki  
Bukit  
Singapore 415875

Estimated Period of Repair: 0.0 days

**Adjuster:** ADRIAN LING**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$310,000.00
OMV :	\$ 62,376.00
PARF Rebate (1) :	\$ 63,207.00
Quota Premium Paid :	\$ 37,500.00
COE Rebate (2) :	\$ 27,416.00
Total Rebate (1) + (2) = :	\$ 90,623.00

The total amount incurred will be Market Value \$310,000.00 minus Total Rebate \$90,623.00 = \$219,377.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Mar 2023)
Parts:	M1-COUPE	FORD MUSTANG 5.0 GT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMT5825U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >