



Your Ref : SNM23D201637/C01

Date: 16th March 2023

Our Ref : CS/CTI23002488/Aqy3m4

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMT 5825U
ACCIDENT ON 28/02/2023**

Instruction was received to inspect the vehicle Reg. No. SMT 5825U. The inspection was conducted on 09/03/2023 at the premises of M/s Xin Yun Auto Pte Ltd, Blk 8 Kaki Bukit Avenue 4, #05-23 Premier @ Kaki Bukit, Singapore 415875.

The following vehicle information was recorded:

Registration Number	: SMT 5825U
Make/Model	: Ford Mustang 5.0GT Auto
Year of Registration	: 2020
Body Colour	: Orange
Chassis Number	: 1FA6P8NF2J5141003
Engine Capacity	: 5038 cc

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 310,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 90,623.00)
Nett Liability	<u>S\$ 219,377.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIAd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.