

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 10 Mar 2023

Preliminary Advice

Vehicle No	: SMT5825U	Accident Date	: 28/02/2023
Make	: FORD MUSTANG	Policy No.	: DMPCSNW00158392200
Assignment Date	: 10/03/2023	Excess	: S\$5,000.00
Date of Inspection	: 09/03/2023	Est. Duration of Repair	: 0
Inspection At	: XIN YUN AUTO PTE LTD (KAKI BUKIT) (HQ) 8 KAKI BUKIT AVENUE 4, #05-23 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRER'S Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	310,000.00
COE / PARF Rebate	:S\$	90,623.00
Salvage Value	:S\$	
Margin for Repair	:S\$	219,377.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :