

**BW WORKSHOP SERVICES PTE LTD**

291 Kaki Bukit Ave 1  
 Shun Li Industrial Park  
 Singapore 416080  
 6289 8800  
 workshop\_admin@bw.com.sg  
 GST Registration No. : 201504834E



67458800  
 97318883

TP China  
 Veron

**Estimates**

**ADDRESS**

CHINA TAIPING INSURANCE  
 (SINGAPORE) PTE LTD  
 3 Anson Rd, #16-00 Springleaf  
 Tower, Singapore 079909

**ESTIMATES NO.** 1530  
**DATE** 06/03/2023

**VIN NUMBER** SLR1208A / GB71012675  
**MAKE & MODEL** HONDA FREED  
**MILEAGE** -

ACTIVITY	QTY	RATE	AMOUNT
REAR TAILGATE @ \$1240 <i>Dented</i> [REPAIR] REAR BUMPER <i>Rep</i>	1	992.00	992.00
			Subtotal: 992.00
REAR WINDSCREEN SEALANT -S/N <i>new</i>	1	80.00	<del>80.00</del> 60
			Subtotal: 80.00
TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	4	200.00	<del>800.00</del> 400
TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	2	200.00	<del>400.00</del> 350
TO TRANSFER TAILGATE'S FITTINGS	1	150.00	<del>150.00</del> 80
TO REMOVE AND REFIT REAR WINDSCREEN	1	150.00	<del>150.00</del> 120
TO REMOVE AND REFIT REVERSE CAMERA	1	120.00	<del>120.00</del> 50
TO APPLY RUST PROOFING ON THE ADJUSTMENT PANELS	1	60.00	<del>60.00</del> x
			Subtotal: 1,680.00

Please feel free to contact us again if you have any queries on our quotation.

SUBTOTAL 2,752.00  
 GST TOTAL 0.00  
**TOTAL SGD 2,752.00**

We look forward to hearing from you soon.

*total: 2052*

*CP/P*

*Admin Lj  
 P/P 15/03/23.*

*037 eng.*

*96893735.*

**PAYMENT METHOD**

> PayNow To 201504834E  
 > Transfer: UOB 356-3051777

Account Name : BW Workshop Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Parts prices must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: