

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 67Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	REAR NUMBER PLATE LAMP @\$102.40 (CONSISTENT)	NOT NECESSARY	204.80	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,985.40	1,795.00
2	REAR BUMPER SIDE HOLDER @\$105.10 (CONSISTENT)	NOT NECESSARY	210.20	-
1	REAR BUMPER TOW COVER (CONSISTENT)	TO REPAIR SEE LABOUR	70.50	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	950.40	-
2	REAR BUMPER REFLECTOR @\$132.50 (CONSISTENT)	NOT NECESSARY	265.00	-
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	CUT	529.90	529.90
1	REAR BUMPER LOWER GARNISH CHROME MOULDING (CONSISTENT)	CRACKED	285.50	285.50
1	REAR BUMPER CENTRE GUIDE (CONSISTENT)	NOT NECESSARY	194.50	-
2	REAR BUMPER EXHAUST CHROME @\$390.40 (CONSISTENT)	NOT NECESSARY	780.80	-
4	REVERSE SENSOR @\$269.00 (CONSISTENT)	DAMAGED (2PCS ONLY)	1,076.00	538.00
4	REVERSE SENSOR HOLDER @\$25.00 (CONSISTENT)	NECESSARY	100.00	100.00
	LESS 10% DISCOUNT		-665.30	-324.84
			5,987.70	2,923.56
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	CRACKED	30.00	30.00
1	REAR NUMBER PLATE HOLDER (SN) (CONSISTENT)	DEFORMED	30.00	30.00
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	50.00
			110.00	110.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER TOW COVER.		400.00	250.00
	SPRAY PAINTING TO AFFECTED AREA.		500.00	250.00
	WIRING CHECK.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,050.00	580.00
	GRAND TOTAL		7,147.70	3,613.56

Report Ref No. CS/HSB23002494/Aqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/HSB23002494/Aqy3e2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.