



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOW GARNET		Ref: CS/HSB23002494/Aqy3e2 Date: 26/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHA 5006B	Veh. Inspected	SGJ 67Y
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04KAF	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	09/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ E300	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WDD2384482F026167	Colour	RED
Odometer	74355 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/35 R19	MICHELIN	6 mm
L/H Front Tyre	275/35 R19	MICHELIN	6 mm
R/H Rear Tyre	275/35 R19	MICHELIN	6 mm
L/H Rear Tyre	275/35 R19	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	08/03/2023	Inspection Date	09/03/2023
Survey held at	AUTOMOBILE HUB ENTERPRISE 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	