

(08/11/13) wof

ASS. REC. BY: James

REF:

CS/CTI 2300 2497/Ray3

2940

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 622Zat Workshop m/s KAH MOTORof MECKENRO RD

Insured:

CTI

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

116K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 622Z

Yr Regn:

2018 / AUG

Type:

M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda odyssey 2.4 EXI 8PCC 2356

Colour

MARoon

A/C:

Insured / Std / NI / NA

Sp. Reading

091329

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JH MRC1890JC 204671

Gen. Cond:

Good / (Fair) / Poor / Burnt

Steering:

(Inorder) / Jammed / Leaked / Burnt or

Brake:

(Inorder) / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/03/23

D.O.I.

20/03/23

Survey held at

KAH MOTOR

Des. of Damages: Frt /

Rear

/ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 68K

Date/Time, File Pass to?



: Prell. Report



: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

epj

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT23000715	Page	1
Registration No	: SKX622Z	Date	: 7. Mar 2023		
Chassis No	: JHMRC1890JC204671	Customer No.	: WZC008		
Model	: ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO	Svc Advisor	: NG SIN HAI		
Owner's Name	: HERMIZAN BIN MOHAMED JUMARI	Engine No	: K24W72402071		
Ins Policy No.	:	Date Time	: 7. Mar 2023 7:13:24 PM		
Date of Accident	: 7/3/2023	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	110.00		30 110.00	8.80	118.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		180 250.00	20.00	270.00
BOJSE	SEALANT FOR REAR END PANEL	1	120.00		X 120.00	9.60	129.60
BOJSE	SEALANT FOR TAILGATE	1	120.00		100 120.00	9.60	129.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00		X 120.00	9.60	129.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		180 250.00	20.00	270.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00		X 650.00	52.00	702.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		325 650.00	52.00	702.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BKBU01R	WINDSCREEN DAMKIT	1	120.00		120.00	9.60	129.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		X 650.00	52.00	702.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	5000.00		1950 5000.00	400.00	5400.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00		1560 3500.00	280.00	3780.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	480.00		X 480.00	38.40	518.40
BKBU01R	RESET AND CALIBRATE ALL SMART ENTRY	1	650.00		580 650.00	52.00	702.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00		580 650.00	52.00	702.00

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKX622Z

Chassis No : JHMRC1890JC204671

Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO

Owner's Name : HERMIZAN BIN MOHAMED JUMARI

Ins Policy No. :

Date of Accident : 7/3/2023

Document No. : SQT23000715 Page 2

Date : 7. Mar 2023

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72402071

Date | Time : 7. Mar 2023 7:13:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	41.60	561.60
Sum Labor					15140.00	1,211.20	16,351.20
RS-TMP3040L	VPC 4PCS REAR SENSORS <i>ru /</i>	1	320.00		320.00	25.60	345.60
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>X</i>	1	45.00		45.00	3.60	48.60
33500-T6A-003	TAILLIGHT ASSYR. <i>X</i>	1	897.20	25	672.90	53.83	726.73
33550-T6A-003	TAILLIGHT ASSYL. <i>X</i>	1	897.20	25	672.90	53.83	726.73
34150-T6A-003	LIGHT ASSY,R.LID <i>X</i>	1	413.40	25	310.05	24.80	334.85
34155-T6A-003	LIGHT ASSYL.LID <i>X</i>	1	413.40	25	310.05	24.80	334.85
74890-T6A-J01	GARNISH ASSYRR.LICENSE <i>X</i>	1	246.70	25	185.02	14.80	199.82
68100-T6A-Q10ZZ	TAILGATE COMP <i>st / ?</i>	1	1146.20	25	859.65	68.77	928.42
74440-T6A-003	WEATHERSTRIPTAILGATE <i>?</i>	1	125.70	25	94.27	7.54	101.81
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN <i>X</i>	1	187.90	25	140.92	11.27	152.19
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER <i>X</i>	1	677.40	25	508.05	40.64	548.69
91513-T6A-003	CLIPTAILGATE SPOILER <i>ru /</i>	6	2.60	25	11.70	0.94	12.64
75701-T6A-000	EMBLEMH <i>ru /</i>	1	28.20	25	21.15	1.69	22.84
04715-T6A-900ZZ	FACERR.BUMPER <i>de -</i>	1	608.30	25	456.22	36.50	492.72
33505-SLJ-013	REFLECTOR ASSYR.RR. <i>X</i>	1	48.50	25	36.37	2.91	39.28
33555-SLJ-013	REFLECTOR ASSYL.RR. <i>X</i>	1	48.50	25	36.37	2.91	39.28
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH <i>X</i>	1	84.70	25	63.52	5.08	68.60
71507-T6A-003ZB	FACE,L.RR.BUMPER GARNISH <i>X</i>	1	84.70	25	63.52	5.08	68.60
71512-T6A-921ZB	SPOILER ASSY,R.RR.SIDE <i>X</i>	1	125.80	25	94.35	7.55	101.90
71517-T6A-921ZB	SPOILER ASSY,L.RR.SIDE <i>X</i>	1	125.80	25	94.35	7.55	101.90
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>ru /</i>	1	20.40	25	15.30	1.22	16.52
71598-T6A-003	SPACERL.RR.BUMPER SIDE <i>ru /</i>	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER <i>ru /</i>	7	2.30	25	12.07	0.97	13.04
66100-T6A-300ZZ	PANEL COMP,RR. <i>repair</i>	1	493.20	25	369.90	29.59	399.49
04656-T6A-300ZZ	PAN SET3RD SEAT <i>X</i>	1	372.60	25	279.45	22.36	301.81
72841-SH3-315	OILSHEET <i>X</i>	3	43.50	25	97.87	7.83	105.70

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

KAH MOTOR CO. SDN. BHD.

Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKX622Z

Chassis No : JHMRC1890JC204671

Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO

Owner's Name : HERMIZAN BIN MOHAMED JUMARI

Ins Policy No. :

Date of Accident : 7/3/2023

Document No. : SQT23000715 Page 3

Date : 7. Mar 2023

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72402071

Date | Time : 7. Mar 2023 7:13:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incl GST
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER X	1	220.80	25	165.60	13.25	178.85
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL X	1	11.50	25	8.62	0.69	9.31
84615-T6A-N71ZD	LINING COMPR.RR.SIDE X	1	809.20	25	606.90	48.55	655.45
84640-T6A-003ZA	LINING ASSYRR.PANEL X	1	110.90	25	83.17	6.65	89.82
84643-T6A-Q01ZA	COMP LIDTOOL X	1	65.70	25	49.27	3.94	53.21
84665-T6A-N71ZD	LINING COMPL.RR.SIDE X	1	841.90	25	631.42	50.51	681.93
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE m /	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER m /	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER m /	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD m /	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER A WINDSHIELD DAM m /	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5 m /	2	9.10	25	13.65	1.09	14.74
76711-T6A-003	CAPPIVOT m /	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N) m /	2	60.00		120.00	9.60	129.60
Sum Item					7540.24	603.19	8,143.43

Survey By Rosme - Up 90010068

Date & Time 20/03/23 P 1130

Excess 5 days

Status For repair before part

Signature [Signature]

Total Amount 22,680.24 1,814.39 24,494.63

Total (Inclusive of GST) 24,494.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	294D
Vehicle Details	
Vehicle No.:	SKX622Z
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Mar 2023
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR NAVI RES
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	K24W72402071
Chassis No.:	JHMRC1890JC204671
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$33,352.00
Original Registration Date:	10 Aug 2018
First Registration Date:	10 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$38,693.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Aug 2028
PARF Rebate Amount:	\$29,019.00
Intended COE Rebate Details	
COE Expiry Date:	09 Aug 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,551.00
COE Rebate Amount:	\$17,535.00
Total Rebate Amount:	\$46,554.00

Honda Odyssey 2.4A EX-S

Overview

Insurance

Financial

Accessories

Similar

Research

Photos



HUA YANG CREDIT PTE LTD



Price **\$115,800**

Depreciation  **\$18,750 /yr**
[View models with similar depre](#)

Reg Date **30-Jul-2018**
(5yrs 4mths 9days COE left)

Mileage **76,000 km (16.4k /yr)**

Manufactured  **2018**

Road Tax  **\$1,630 /yr**

Transmission **Auto**

Dereg Value  **\$42,846 as of today (change)**

OMV  **\$27,448**

COE  **\$37,330**

ARF  **\$30,428**

Engine Cap **2,356 cc**

Power **129.0 kW (172 bhp)**

Curb Weight  **1,776 kg**

No. of Owners  **1**