

(08/11/13) wef

ASS. REC. BY:

REF:

CS/CTI 23002497/Rny3

2940

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKX 622Z

at Workshop m/s KAH MOTOR

of MCKINNON RD

Insured:

CTI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

116k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 622Z

Yr Regn:

2018 / AUG

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA ODYSSEY 2.4 EX S/R.c.c 2356

Colour:

MAROON

A/C: Insured / Std / NI / NA

Sp. Reading

091329

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH MRC1890JC 204671

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/03/23

Rear

R/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

20/03/23

Survey held at

KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 68k

Confirmed final fig \$8562.62 and 5 days

(Red. \$14216.9, 62%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

5

1) 16/5/23

☐

: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SKX622Z

Chassis No : JHMRC1890JC204671

Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO

Owner's Name : HERMIZAN BIN MOHAMED JUMARI

Ins Policy No. :

Date of Accident : 7/3/2023

Document No. : SQT23000715 **Page** 1

Date : 7. Mar 2023

Customer No. : WZC008

Svc Advisor : NG SIN HAI

Engine No : K24W72402071

Date | Time : 7. Mar 2023 7:13:24 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	110.00		110.00	8.80	118.80
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	20.00	270.00
BOJSE	SEALANT FOR REAR END PANEL	1	120.00		120.00	9.60	129.60
BOJSE	SEALANT FOR TAILGATE	1	120.00		120.00	9.60	129.60
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00		120.00	9.60	129.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	20.00	270.00
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00		650.00	52.00	702.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	52.00	702.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	52.00	702.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	52.00	702.00
BKBU01R	WINDSCREEN DAMKIT	1	120.00		120.00	9.60	129.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	52.00	702.00
BKRP02M	CUT OFF & RENEW RR PANEL.	1	5000.00		5000.00	400.00	5400.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00		3500.00	280.00	3780.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	480.00		480.00	38.40	518.40
BKBU01R	RESET AND CALIBRATE ALL SMART ENTRY	1	650.00		650.00	52.00	702.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00		650.00	52.00	702.00

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKX622Z
Chassis No : JHMRC1890JC204671
Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO
Owner's Name : HERMIZAN BIN MOHAMED JUMARI
Ins Policy No. :
Date of Accident : 7/3/2023

Document No. : SQT23000715 Page 2
Date : 7. Mar 2023
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24W72402071
Date | Time : 7. Mar 2023 7:13:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	41.60	561.60
Sum Labor					<u>15140.00</u>	<u>1,211.20</u>	<u>16,351.20</u>
RS-TMP3040L	VPC 4PCS REAR SENSORS nn X nn	1	320.00		320.00	25.60	345.60
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) nn X nn	1	45.00		45.00	3.60	48.60
33500-T6A-003	TAILLIGHT ASSYR. X	1	897.20	25	672.90	53.83	726.73
33550-T6A-003	TAILLIGHT ASSYL. X } nn	1	897.20	25	672.90	53.83	726.73
34150-T6A-003	LIGHT ASSY,R.LID X } nn	1	413.40	25	310.05	24.80	334.85
34155-T6A-003	LIGHT ASSYL.LID X } nn	1	413.40	25	310.05	24.80	334.85
74890-T6A-J01	GARNISH ASSYRR.LICENSE X nn	1	246.70	25	185.02	14.80	199.82
68100-T6A-Q10ZZ	TAILGATE COMP st X nn	1	1146.20	25	859.65	68.77	928.42
74440-T6A-003	WEATHERSTRIPTAILGATE X nn	1	125.70	25	94.27	7.54	101.81
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN X nn	1	187.90	25	140.92	11.27	152.19
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER X nn	1	677.40	25	508.05	40.64	548.69
91513-T6A-003	CLIPTAILGATE SPOILER nn	6	2.60	25	11.70	0.94	12.64
75701-T6A-000	EMBLEMH nn	1	28.20	25	21.15	1.69	22.84
04715-T6A-900ZZ	FACERR.BUMPER de	1	608.30 562	25 421.50	456.22	36.50	492.72
33505-SLJ-013	REFLECTOR ASSYR.RR. X	1	48.50	25	36.37	2.91	39.28
33555-SLJ-013	REFLECTOR ASSYL.RR. X	1	48.50	25	36.37	2.91	39.28
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH X } nn	1	84.70	25	63.52	5.08	68.60
71507-T6A-003ZB	FACE,L.RR.BUMPER GARNISH X } nn	1	84.70	25	63.52	5.08	68.60
71512-T6A-921ZB	SPOILER ASSY,R.RR.SIDE X } nn	1	125.80	25	94.35	7.55	101.90
71517-T6A-921ZB	SPOILER ASSY,L.RR.SIDE X } nn	1	125.80	25	94.35	7.55	101.90
71593-T6A-003	SPACERR.RR.BUMPER SIDE nn	1	20.40	25	15.30	1.22	16.52
71598-T6A-003	SPACERL.RR.BUMPER SIDE nn	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER nn	7	2.30	25	12.07	0.97	13.04
66100-T6A-300ZZ	PANEL COMP,RR. repair	1	493.20	25	369.90	29.59	399.49
04656-T6A-300ZZ	PAN SET3RD SEAT X nn	1	372.60	25	279.45	22.36	301.81
72841-SH3-315	OILSHEET X nn	3	43.50	25	97.87	7.83	105.70

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SKX622Z
Chassis No : JHMRC1890JC204671
Model : ODYSSEY2.4 EXV-S 18YM NAVI-RES (EURO
Owner's Name : HERMIZAN BIN MOHAMED JUMARI
Ins Policy No. :
Date of Accident : 7/3/2023

Document No. : SQT23000715 Page 3
Date : 7. Mar 2023
Customer No. : WZC008
Svc Advisor : NG SIN HAI
Engine No : K24W72402071
Date | Time : 7. Mar 2023 7:13:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER X N3	1	220.80	25	165.60	13.25	178.85
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL X N3	1	11.50	25	8.62	0.69	9.31
84615-T6A-N71ZD	LINING COMPR.RR.SIDE X N3	1	809.20	25	606.90	48.55	655.45
84640-T6A-003ZA	LINING ASSYRR.PANEL X N3	1	110.90	25	83.17	6.65	89.82
84643-T6A-Q01ZA	COMP LIDTOOL X N3	1	65.70	25	49.27	3.94	53.21
84665-T6A-N71ZD	LINING COMPL.RR.SIDE X N3	1	841.90	25	631.42	50.51	681.93
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.30	31.10
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	1.09	14.66
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	1.01	13.61
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.23	3.15
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	1.09	14.74
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.31	4.21
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	9.60	129.60
Sum Item					7540.24	603.19	8,143.43

Survey By : Rosie - 4p 90010568
Date & Time : 20/03/23 01130
Excess : 5 days
Status :
Signature : [Signature]

22719.53
Total Amount 22,680.24 1,814.39 24,494.63
Total (Inclusive of GST) 24,494.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 8/3/2023 9:15:50 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0100138 / HERMIZAN BIN
Chassis No: JHMRC1890JC204671
License No: SKX622Z
Mileage: 90275
Engine No: K24W72402071

Document No: SVO23011473
Printed By: SHNG
Order Date: 20. March 2023
Order Time: 12:37:07 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	8% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
75722-T6A-901	EMBLEM,RR. <i>m</i>	1	33.20	25	24.90	1.99	26.89
39683-T6A-N11ZA	RETAINER,PARKING <i>m</i>	1	44.70	25	33.52	2.68	36.20
39684-T6A-N01ZA	RETAINER,PARKING D <i>m</i>	1	44.70	25	33.52	2.68	36.20
	SUM PARTS:				91.94	7.35	99.29
	TOTAL SGD				91.94	7.35	99.29

Total Payable (SGD)

99.29

GST Amount is calculated from individual line(s)