



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002498/Avy3e2 Date: 14/05/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 8761D	Veh. Inspected	SNG 7609X
Policy No.	D-22099601MFCV/8	Coverage (\$)	0.00
Claim No.	D23000813MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	09/03/2023
2. Vehicle Particulars & Condition			
Make & Model	AUDI Q5	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WAUZZZ8R6AA048454	Colour	BLACK
Odometer	154306 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/45 R20	CONTINENTAL	6 mm
L/H Front Tyre	255/45 R20	CONTINENTAL	6 mm
R/H Rear Tyre	255/45 R20	CONTINENTAL	6 mm
L/H Rear Tyre	255/45 R20	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/03/2023	Inspection Date	09/03/2023
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days	