

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921
 Email: ryderautoworkshop@gmail.com
 Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# SNG7609X

Model: AUDI Q5

Accident Date 7/3/2023

Veron.
 TP 1st Cap

(12/4/2010-11/4/2030)

Location : PIE (TUAS) AFTER TOH TUCK ROAD EXIT

3P: YP8761D (FIRST CAP)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front grille <i>Cracked.</i>	1008.10	✓	
2	1 pc	Front grille moulding garnish <i>Not nec</i>	209.00	X	
3	1 pc	Front grille logo <i>New</i>	166.10	✓	
4	1 pc	Front grille upper cover <i>Deformed</i>	131.70	✓	
5	1 set	Front grille upper cover clips <i>New</i>	136.90	✓	50.00 20.
6	1 pc	Front grille emblem -QUATTRO- <i>Nec</i>	4,620.00	✓	2310.
7	2 pcs	Front headlamp R/L <i>LH cracked.</i>	357.80	✓	
8	2 pcs	Front headlamp lower bracket R/L <i>could</i>	190.20	X	
9	2 pcs	Front headlamp side bracket R/L <i>Not nec</i>	393.40	✓	
10	2 pcs	Front headlamp panel bracket R/L <i>could</i>	1,050.00	✓	
11	1 pc	Front bumper <i>Deformed</i>	196.20	✓	
12	2 pcs	Front bumper side retainer R/L <i>could</i>	619.70	✓	
13	1 pc	Front bumper reinforcement <i>Dented.</i>	157.50	✓	
14	1 pc	Front bumper inner sponge <i>Cracked</i>	463.40	✓	231.70
15	2 pcs	Front bumper fog lamp cover R/L <i>LH ut</i>	531.10	X	
16	1 pc	Front bumper lower lid garnish <i>Not nec</i>		✓	80.00 50
17	1 set	Front bumper clips <i>New</i>	262.50	✓	
18	1 pc	Front bumper fog lamp LH <i>Cracked</i>	45.00	X	
19	1 pc	Front bumper washer cover LH <i>Not nec</i>	266.10	✓	
20	1 pc	Front bumper washer nozzle LH <i>Damaged</i>		✓	45.00 30
21	1 pc	Front number plate <i>Dented</i>		✓	50.00 30.
22	1 pc	Front number plate holder <i>Deformed</i>	945.10	✓	
23	1 pc	Front support panel carrier <i>Cracked</i>	660.90	X	
24	1 pc	Radiator (Auto) <i>Not nec</i>		✓	60.00 40.
25	1 pc	Radiator coolant <i>New</i>	2835.10	✓	
26	1 pc	Rear tailgate <i>Distorted</i>		✓	800.00 580.
27	1 pc	Rear tailgate recorder camera <i>Damaged</i>	671.90	✓	
28	1 pc	Rear tailgate top spoiler <i>Damaged.</i>		✓	50.00 30.
29	1 set	Rear tailgate top spoiler clips <i>Nec</i>	222.90	X	
30	1 pc	Rear tailgate third brake lamp <i>Not nec</i>	190.20	✓	
31	2 pcs	Rear tailgate hinges R/L <i>Best</i>	399.00	X	
32	2 pcs	Rear tailgate damper R/L <i>Not nec</i>	165.90	✓	
33	1 pc	Rear tailgate inner upper trim cover <i>Deformed</i>		✓	50.00 20.
34	1 set	Rear tailgate inner upper trim cover clips <i>New</i>	299.00	✓	
35	1 pc	Rear tailgate inner trim cover <i>Deformed</i>		✓	50.00 30
36	1 set	Rear tailgate inner trim cover clips <i>New</i>		✓	
37	1 pc	Rear tailgate windscreen glass <i>Shattered</i>	2911.70	✓	100.00 40
38	1 pc	Rear tailgate windscreen glass seal <i>New</i>		✓	80.00 30.
39	1 pc	Rear tailgate windscreen glass sealant <i>New</i>		✓	480.00 200
40	1 pc	Rear tailgate windscreen glass solar film <i>New</i>		✓	
41	1 pc	Rear tailgate wiper motor <i>Damaged</i>	669.70	✓	
42	1 pc	Rear tailgate wiper arm <i>Damaged</i>	166.20	✓	
43	1 pc	Rear tailgate wiper arm cover <i>Damaged</i>	41.50	✓	
44	1 pc	Rear tailgate wiper blade <i>ut</i>	195.70	✓	
45	1 pc	Rear tailgate logo <i>New</i>	166.50	✓	

46	1 pc	Rear tailgate emblem -SQ5-		145.90	✓		
47	1 pc	Rear tailgate emblem -2.OT-	} Nec	110.70	✓		
48	1 pc	Rear tailgate emblem -QUATTRO-	} Nec	100.50	✓		
49	2 pcs	Rear tailgate reflector R/L	cracked	2401.80	✓		
50	2 pcs	Rear tailgate reflector gasket seal R/L	new	40.00	✓		
51	1 pc	Rear tailgate opener button switch	Not New	144.00	X		
52	1 pc	Rear tailgate reverse camera	Damaged			500.00	380.
53	1 pc	Rear tailgate mechanism lock	Damaged	195.10	✓		
54	1 pc	Rear tailgate mechanism lock sticker	Bent	66.70	✓		
55	1 pc	Rear tailgate weatherstrip	cut	245.60	✓		
56	2 pcs	Rear tailgate guide rubber stopped R/L	not new	70.00	X		
57	1 pc	Rear tailgate mechanism lock sticker motor	Damaged	296.70	✓		
58	2 pcs	Rear tailgate inner side trim cover R/L	Deformed	883.40	✓		
59	1 pc	Rear bumper (Top)	} Distorted	1890.10	✓		
60	1 pc	Rear bumper (Bottom)	} Distorted	737.00	✓		
61	2 pcs	Rear bumper tow hook cover R/L	Deformed	90.00	✓		
62	1 pc	Rear bumper reinforcement	Bent	453.60	✓		
63	4 pcs	Rear bumper reverse sensor	3 pieces damaged.	967.60	✓	725.70	
64	4 pcs	Rear bumper reverse sensor 'O' ring	new	60.00	✓		
65	4 pcs	Rear bumper reverse sensor holder bracket	Damaged	180.00	✓		
66	1 pc	Rear bumper reverse sensor wire harness	snapped.	262.10	✓		
67	1 pc	Rear bumper top rubber pad	Nec			400.00	280.
68	2 pcs	Rear bumper reinforcement bracket R/L	Bent	350.20	✓		
69	1 pc	Rear bumper inner frame bracket	cracked	207.60	✓		
70	2 pcs	Rear bumper side retainer R/L	cracked	270.00	✓		
71	2 pcs	Rear bumper lamp R/L	cracked.	653.80	✓		
72	2 pcs	Rear bumper reinforcement sponge R/L	not Deformed	110.00	✓		
73	2 pcs	Rear exhaust silencer R/L	Repair Bent.	1532.20	X		
74	2 pcs	Rear exhaust rubber mounting R/L	} Not	198.20	X		
75	2 pcs	Rear exhaust chrome tail pipe R/L	} Nec	231.40	X		
76	1 pc	Rear exhaust gasket kit	new			100.00	X
77	2 pcs	Rear exhaust aluminium heat shield R/L	crumpled	555.00	✓		
78	1 pc	Rear fender LH	Repair	1856.70	X		
79	1 pc	Rear fender glass weatherstrip	?	192.00	X		
80	1 pc	Rear fender glass sealant	} Not New			80.00	X
81	1 pc	Rear fender sealant				60.00	X
82	2 pcs	Rear fender inner trim garnish R/L	cracked	667.80	✓		
83	2 sets	Rear fender inner trim garnish clips R/L	new			100.00	60.
84	2 pcs	Rear fender side vertical panel R/L	Dented	603.00	✓		
85	1 pc	Rear end panel (Outer)	} Distorted	544.90	✓		
86	1 pc	Rear end panel (Inner)		466.70	✓		
87	1 pc	Rear end panel inner top garnish	Deformed	205.00	✓		
88	1 set	Rear end panel inner top garnish clips	new			40.00	20.
89	1 pc	Rear end panel sealant	new			180.00	60.
90	1 pc	Rear number plate	Bent			45.00	30
91	1 pc	Rear number plate holder	Deformed			50.00	30
92	2 pcs	Rear number plate lamp R/L	cracked	423.18	✓		
93	1 pc	Roof top lining	Not New	1911.70	X		
94	1 pc	Dashboard screen monitor unit	Damaged	3351.70	✓		
95	2 pcs	Rear exhaust rubber mounting bracket R/L	Not New	170.00	X		280
96	1 pc	Rear battery	Damaged			600.00	
97	1 pc	Rear battery fuse unit	Activated	505.00	✓		
98	1 pc	Rear battery cap cover	Deformed	75.50	✓		
99	2 pcs	Rear end side panel R/L	Dented	399.40	✓		
100	2 pcs	Rear end side panel air vent R/L	Not new	181.40	X		
101	1 pc	Rear battery tool cover	Deformed	202.10	✓		
102	1 pc	Rear tool sponge tray	Cracked	186.20	✓		
103	1 pc	Rear floor trim mat	Not new	333.90	X		
104	2 pcs	Rear floor lower side trim R/L	Deformed	599.00	✓		
105	1 pc	Rear floor trim mat cover	Torn	155.10	✓		
106	1 pc	Rear spare tyre top board cover	Damaged	444.90	✓		
107	1 pc	Rear keyless antenna sensor	cracked	195.00	✓		

108	1 pc	Rear brake control unit module RH <i>Damaged</i>	1575.10		
109	1 pc	Rear fuse box casing RH <i>Not new</i>	199.50		
110	2 pcs	Front safety belt R/L <i>3 New Adjusted</i>	2731.80	1800	1500
111	1 pc	Air bag control unit	9340.90	5.950	950
Sub Total:			55,282.68	4,050.00	0.00
			5%	0%	0%
After Less %:			52,518.55	4050.00	0.00

1800

*A) 490.58
38 241.52 SNI: 2240*

Labour		
1	To remove & refix accident damaged parts & realign affected area.	3,000.00 2200
2	To spray paint accident affected area.	2,500.00 2300
3	To remove & refix air-con parts & refiling gas.	150.00 60
4	To remove & refix radiator, fan motor & hose.	120.00 60
5	To remove & refix rear tailgate windscreen glass.	200.00 120
6	To remove & refix rear tailgate mechanism, motor & check for function.	100.00 80
7	To remove & refix rear upholstery, cushion seat, trim garnish & other attachment parts.	250.00 120
8	To cleaning, shampoo cushion seat & upholstery.	180.00 80
9	To remove & refix wiring harness, check lighting & rewire parking sensor.	150.00 100
10	To check, diagnosis & reset after work.	400.00 180
11	To rust proof affected area.	120.00 100
12	To remove & refix exhaust pipe.	200.00
Sub Total:		7,370.00
Total:		63,938.55

5200

Chan
Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

*Adrian Lj
H/S 09/03/23
18 Days.*



biSAFE AL 8778 1999
24 hr accident call



Total: 45881.52

H/S: 36.5K

36.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: