



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:VALE OH		Ref: CC4/HSB23002500/Tpa3q2 Date: 14/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7694R	Veh. Inspected	JVK 9298
Policy No.	P2478220	Coverage (\$)	0.00
Claim No.	S3M04K72	Excess (\$)	0.00
Assign From		Assign Date	09/03/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA INNOVA	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	PN111NV4018644264	Colour	BLACK
Odometer	168895 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	TOYO	6 mm
L/H Front Tyre	205/65 R15	TOYO	6 mm
R/H Rear Tyre	205/65 R15	TOYO	6 mm
L/H Rear Tyre	205/65 R15	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/03/2023	Inspection Date	09/03/2023
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	