

KW

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: HYUNDAI ELANTRA

Engine/Chassis No.: KMHD841CMJU767552

Date of accident: 05.03.23


Damaged area: Rear

Date: 28/03/2023

Claim Type: TP

VRN: SMF4023Y

NOT AUTHORIZED
11km @ 1250/h
Murry After Paint



3 days

List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear Bumper 43P-40 MyoM/Blue	1	\$ 983.00	\$ 983.00	
2	Rear Bumper diffuser 231-10 Not 100%	1	\$ 467.00	\$ 467.00	
3	Rear Bumper lower cowl	1	\$ 314.00	\$ 314.00	
4	Rear Bumper reflector	2	\$ 255.00	\$ 510.00	
5	Rear Bumper splash guard	2	\$ 95.00	\$ 190.00	
6	Rear Bumper reinforcement support bracket	5	\$ 36.00	\$ 180.00	
7	Rear Bumper reinforcement 295	1	\$ 659.00	\$ 659.00	
8	Rear Bumper reinforcement side bracket	2	\$ 129.00	\$ 258.00	
9	Rear bumper side retainer	2	\$ 65.00	\$ 130.00	
10	Rear licence plate lamp	2	\$ 143.00	\$ 286.00	
11	Rear bumper licence plate base	1	\$ 59.00	\$ 59.00	
12	End panel	1	\$ 732.00	\$ 732.00	
13	End panel top garnish	1	\$ 177.00	\$ 177.00	
Subtotal				\$ 4,945.00	
List discount				20.00%	
Total				\$ 3,956.00	

Special nett items					
No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear Bumper clips	12	\$ 4.50	\$ 54.00	
2	Rear licence plate & frame	1	\$ 55.00	\$ 55.00	
3	End panel top garnish clips	8	\$ 4.50	\$ 36.00	
4	Reverse sensor	1	\$ 280.00	\$ 280.00	
5	End panel sealant	1	\$ 100.00	\$ 100.00	
6	Sundries	1	\$ 50.00	\$ 50.00	
Total				\$ 575.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check functions.	0.25	\$ 50.00
3	To remove, replace reverse sensors and check for proper function.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To rust proof accident affected portions.	0.5	\$ <i>nm</i> 100.00
Total labour			\$ 2,450.00
Estimate Grand Total			\$ 6,981.00

300/

13/

50/

400/

X