



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 3700H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	200.00	100.00
1	COVER, OUTER MIRROR (SN)	MISSING	158.10	158.10
1	MIRROR ASSY, OUTER (SN)	CUT	1,554.10	1,554.10
1	TAPE, BLACK OUT (SN)	NECESSARY	57.70	57.70
1	STRIPE, FR DOOR (SN)	NECESSARY	36.80	36.80
1	STRIPE, FR DOOR (SN)	NECESSARY	26.30	26.30
	STRIPE, FR DOOR (SN)	NECESSARY	18.60	18.60
1	PANEL SUB-ASSY, FR (SN)	BENT	1,563.20	1,563.20
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	117.20	-
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	133.20	-
1	HANDLE ASSY, FR (SN)	SCRATCHED	469.10	469.10
1	COVER, FR DOOR (SN)	SCRATCHED	18.20	18.20
1	COVER ASSY, DOOR (SN)	NOT NECESSARY	40.40	-
1	PANEL SUB-ASSY, RR (SN)	TO REPAIR SEE LABOUR	1,556.50	-
1	TAPE, BLACK OUT (SN)	NOT NECESSARY	57.70	-
1	STRIPE, RR DOOR (SN)	NOT NECESSARY	26.30	-
1	STRIPE, RR DOOR (SN)	NOT NECESSARY	31.70	-
1	STRIPE, RR DOOR (SN)	NOT NECESSARY	26.30	-
1	PROTECTOR, QUARTER (SN)	NECESSARY	27.60	27.60
			6,219.00	4,079.70
LABOUR				
CHECK WIRING UPON COMPLETION OF REPAIR.			240.00	240.00
TRANSFER RH FRT AND REAR DOOR MECHANISM.			792.00	396.00
TO RESET ECU AND REPROGRAMME.			198.00	198.00
REPL ACC AFF PARTS AND PANEL. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, RR.			3,168.00	2,376.00
RESPRAY ACC AFF AREA.			4,592.00	2,952.00
			8,990.00	6,162.00
GRAND TOTAL			15,209.00	10,241.70



RECOMMENDED COST OF REPAIRS			10,241.70
------------------------------------	--	--	------------------

Report Ref No. CS/FCI23002508/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.