

(03/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/AIS23002513/4943

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.A.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\* Cor until 31-12-2027 + H&S 5875  
 need admen report fell on LHS side of vehicle  
 Cost cor 6102 + NEA 2k = 8102 body 1k = 9k.  
 Net 2625

5/4/23 4/5 \$2300 in hand 44R 700.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ )

Add Fee:

☐

: Site Insp (\$ )

☐

: Interview (\$ )

☐

: Tech. Invs (\$ )

☐

: Weekend (\$ )

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Allianz

Owner : Chan Loon Watt (91556932)

Accident Date : 06-Mar-23

Vehicle No : FC2576E (COE311227)

Vehicle Model : Yamaha RXK

## Estimated Repair Costs

| Qty | Description            |                  | Amount S(\$) |
|-----|------------------------|------------------|--------------|
|     | <u>List Items</u>      |                  |              |
| 1   | Front fender           | not Allianz      | 280.00       |
| 2   | Fork inner tubes       | 10/3/23 205 3erf | 650.00       |
| 2   | Fork outer tubes       | 2/5 2300         | 650.00       |
| 1   | Fork under bracket     | 4 days           | 320.00       |
| 1   | Front bracket disc     | take the other 4 | 280.00       |
| 1   | Front sport rim        |                  | 580.00       |
| 1   | Front rim shaft        |                  | 120.00       |
| 1   | Front rim bearing      |                  | 90.00        |
| 1   | Lampstay               |                  | 300.00       |
| 1   | Headlamp               | 300              | 480.00       |
| 2   | Side mirrors           | 68x2=136         | 240.00       |
| 2   | Front signals          |                  | 180.00       |
| 1   | Handle-bar             |                  | 385.00       |
| 1   | Hand grip (1 set)      |                  | 110.00       |
| 2   | Handle bar ends        |                  | 145.00       |
| 1   | Clutch lever           | 68               | 135.00       |
| 1   | Meter assy             | 11               | 1,300.00     |
| 1   | Fuel tank              | 950              | 1,150.00     |
| 1   | Front footrest (1 set) | 115              | 250.00       |
| 1   | Front footrest rubber  | 40x2=80          | 110.00       |
| 1   | Gear pedal             | 125              | 180.00       |
| 1   | Exhaust assy           | 680              | 1,150.00     |
| 1   | Rear signals (1 set)   | 11               | 180.00       |
|     |                        |                  | \$ 9,265.00  |
|     |                        |                  | \$ 926.50    |
|     |                        |                  | \$ 8,338.50  |

## Special Net Items

|   |                       |     |             |
|---|-----------------------|-----|-------------|
| 1 | Number plate (1 set)  | Rec | 38.00       |
| 2 | Fork oils             |     | 38.00       |
| 2 | Fork oil seals        |     | 62.00       |
| 1 | Steering cone (1 set) |     | 120.00      |
| 1 | Rear box              |     | 580.00      |
| 1 | Rear box bracket      |     | 180.00      |
|   |                       |     | \$ 1,018.00 |

# EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Chan Loon Watt (91556932)

Accident Date : 06-Mar-23

Vehicle No : FC2576E (COE311227)

Vehicle Model : Yamaha RXK

## Estimated Repair Costs

| S/No.       | Labour                                      |                |
|-------------|---------------------------------------------|----------------|
| 1           | To provide towing service (LOD) S\$70.00    | \$ -           |
| 2           | To ckeck wiring and reset headlamp focusing | \$ 11 80.00 X  |
| 3           | To repair body frame                        | \$ 11 380.00 X |
| 4           | To provide labour                           | \$ 480.00 300  |
|             |                                             | \$ 940.00      |
| Grand Total |                                             | \$ 10,296.50   |

Singapore Dollars: Ten Thousand Two Hundred Ninety-Six and Cents: Fifty only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-2948  
102  
2054.1