

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 09.03.2023

TO : EQ MOTOR CLAIMS DEPTS
VEHICLE NO : SMD7742X
MODEL : TOYOTA PRIUS
DATE OF ACCIDENT : 08.03.2023
TIME OF ACCIDENT : 13:55 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE INNER LOCK <i>2 x p</i>	1	\$ 447.40	\$ 447.40
2	TAILGATE LOCK CATCH <i>1 x p</i>	1	\$ 29.00	\$ 29.00
3	TAILGATE WEATHER STRIP	1	\$ 281.90	\$ 281.90
4	REAR BUMPER (UPPER) <i>Dehnd</i>	1	\$ 978.70	\$ 978.70
5	REAR BUMPER (LOWER) <i>Dehnd</i>	1	\$ 565.40	\$ 565.40
6	REAR BUMPER LAMP <i>cnld</i>	2	\$ 443.40	\$ 886.80
7	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 26.90	\$ 26.90
8	REAR BUMPER CENTER BOTTOM GARNISH <i>ton</i>	1	\$ 168.00	\$ 168.00
9	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 568.90	\$ 568.90
10	REAR BUMPER SIDE INNER GARNISH <i>Lt torn</i>	2	\$ 158.70	\$ 317.40
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 112.70	\$ 225.40
12	TAILLAMP <i>Rt cnld</i>	2	\$ 469.00	\$ 938.00
13	REAR FENDER INNER COWLING <i>3 x p</i>	2	\$ 194.00	\$ 388.00
14	REAR FENDER INNER TRIM <i>1 x p</i>	2	\$ 612.20	\$ 1,224.40
15	REAR END PANEL <i>Dent</i>	1	\$ 657.00	\$ 657.00
16	REAR END PANEL TOP GARNISH <i>Dehnd</i>	1	\$ 120.70	\$ 120.70
17	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 391.00	\$ 391.00
18	REAR FLOOR TOP SPONGE <i>cnld</i>	1	\$ 185.00	\$ 185.00
19	REAR FLOOR TOOLS TRAY <i>new</i>	1	\$ 125.40	\$ 125.40

TO : **EQ** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMD7742X**
 MODEL : **TOYOTA PRIUS**
 DATE OF ACCIDENT : 08.03.2023
 TIME OF ACCIDENT : 13:55 HOURS

TOTAL PRICE	\$	8,525.30
LESS 25%	\$	2,131.33
SUB TOTAL PRICE	\$	6,393.98

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
2	REAR BUMPER (UPPER) CLIP (SET) <i>3 over</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
3	REAR BUMPER (LOWER) CLIP (SET) <i>3 over</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
4	REAR BUMPER SIDE INNER GARNISH CLIP (SET) <i>Mr</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
5	REAR BUMPER CENTER BOTTOM GARNISH CLIP (SET) <i>Mr</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
14	TAILLAMP CLIP (SET) <i>Mr</i>	1	\$ 40.00	\$ 40.00 <i>10</i>
15	REAR FENDER INNER COWLING CLIP (SET) <i>Mr</i>	1	\$ 50.00	\$ 50.00 <i>+</i>
16	REAR FENDER INNER TRIM CLIP (SET) <i>Mr</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
18	REAR END PANEL INSULATION SEAL <i>Mr</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
19	REAR END PANEL TOP GARNISH CLIP (SET) <i>Mr</i>	1	\$ 50.00	\$ 50.00 <i>20</i>
20	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>20</i>

TOTAL \$ 830.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	<i>600</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>400 400</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING AND BULB CHECK	\$ 380.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>X</i>

TO : **EQ** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMD7742X**
MODEL : **TOYOTA PRIUS**
DATE OF ACCIDENT : 08.03.2023
TIME OF ACCIDENT : 13:55 HOURS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
---	--	-----------	---

TOTAL

4260

ESTIMATE REPORT

TOTAL PARTS COST : \$7,223.98
TOTAL LABOUR COST : \$4,260.00
TOTAL REPAIR COST : \$11,483.98

Adrian L
L/s 23/03/23.
05 days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787