



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNH6534D

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62374
Reg No/Reg Date SNH6534D / 17/11/2022
Date In/Mileage 0
Chassis No W1K2130532B0407449
Engine No 27492032012379
Make/Model MB/E 300 e SEDAN
Colour/Trim 021 197 Obsidian Bl/ 042 214 Rough Leath

Account No	Terms	Date/Time Printed	CSE	Operator			
WA000001	Credit	12/01/2023/ 10:53	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M-BPNSUN

POLICY NO/ACC DATE : SP2003915046 // 11/01/2023
DRIVE IN/EXCESS : 12/01/2023 // TBA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH

A BPIRES

RESPRAY REAR BUMPER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO
STANDARD SETTINGS. NETT

A BPILAB

CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET

M REAR BUMPER

M RIGHT REAR BUMPER LATERAL SUPPORT X NN

M RIGHT REAR BASIC CARRIER, BUMPER X NN

1.00 987.75 00.00 987.75
1.00 89.31 00.00 89.31
1.00 83.28 00.00 83.28

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanzhoe.yik@cyclecarriage.com.sg

Rasul

Hp 9000068

3 days

09/03/23 @ 1550

EXCESS: TBA

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and

The repairer is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplemental invoice must be resurveyed and

is subject to final approval from insurance company

informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or

cheque. You must also agree to pay Acknowledged by Repairer of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

Signature:

Date:

Rasy before print

REVERI

Nett 4,060.34
8% GST on 4060.34 324.83

Total Payable 4,385.17

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. The repairer must be resurveyed and is subject to final approval from insurance company after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay Acknowledged by Repairer of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg