



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

Finalization

## ESTIMATE FOR SNH6534D

ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.  
MOTOR CLAIM DEPARTMENT  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897  
67143369

### Vehicle & Document Information

WIP No **62374**  
Reg No/Reg Date **SNH6534D / 17/11/2022**  
Date In/Mileage **09/03/2023 / 5254**  
Chassis No **W1K2130532B0407449**  
Engine No **27492032012379**  
Make/Model **MB/E 300 e SEDAN**  
Colour/Trim **021 197 Obsidian Bl/ 042 214 Rough Leath**

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	25/03/2023/ 12:35		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : SP2003915046 // 11/01/2023 DRIVE IN/EXCESS : 12/01/2023 // \$700.00 DATE IN/DATE SURVEY: 09/03/2023 @ 1550 // RASUL LKK BY/AUTHORIZED ON : 09/03/2023 @ 1550 // RASUL LKK				960.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH			0.05	800.00
A BPIRES RESPRAY REAR BUMPER			0.10	380.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT				120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET				-700.00
X BPNEXC INSURANCE EXCESS				
X REAR BUMPER	1.00	987.75	00.00	987.75

Attn: **Rasul**

**03** Working Days

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

8% GST on **Nett 2,547.75**  
**203.82**  
**Total Payable 2,751.57**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818  
Fax: 6779 5383  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG