

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 13 Jun 2023

Preliminary Advice

Insured Vehicle No	: GBF8969Y	Accident Date	: 06/03/2023
TP Vehicle No	: SJH3922J	Assignment Date	: 07/03/2023
Make	: MERCEDES-BENZ GLC300	Est. Duration of Repair	: 5
Date of Inspection	: 07/03/2023		
Inspection At	: JD MOTORSPORTS PTE LTD (HQ) 25 KAKI BUKIT ROAD 4, #05-76 SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,856.50
Revised Amount	:S\$	13,776.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,776.45
 Lump Sum Repair	 :S\$	 11,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.