

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0248/2023/EQ
DATE : 6-Mar-23
WIP : 10529

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/3/2023

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR GLYN CARROLL
ADDRESS : 12 HOLLAND HILL
#02-07
SINGAPORE 278743
TELEPHONE : HP +65 90998615
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210000351-01
VEHICLE NO : **SLK 2967 Y**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 14/1/2021
ENGINE NO : CZD C23836
CHASSIS NO : WAUZZZF34M1064798
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Mar-23
PLACE OF ACCIDENT : CAR PARK AT VIVOCITY, BASEMENT 1 CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLK 2967 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N \$	800.00	
2	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. S/N \$	360.00	X 11
3	TO DISMANTLE AND RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS FRONT FENDER AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	4,000.00	1500
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS REAR DOOR, HINGES, LHS REAR FENDER AND REAR BUMPER. \$	5,000.00	1650
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00	
TOTAL LABOUR CHARGES		: \$ 10,352.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 2967 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH <i>bt/</i>	1	\$	3,192.00 <i>2553.60</i>
2	FRONT DOOR OUTER SEAL - LH <i>m/</i>	1	\$	196.00 <i>156.40</i>
3	FRONT DOOR ATTACHMENT PARTS <i>xnn</i>	1	\$	173.00
4	FRONT DOOR CATCH <i>xnn</i>	1	\$	141.00
5	FRONT DOOR COVER - LH <i>su/</i>	1	\$	299.00 <i>239.20</i>
6	FRONT WINDOW REGULATOR - LH <i>? xnn</i>	1	\$	321.00
7	REAR DOOR - LH <i>bt/</i>	1	\$	3,313.00 <i>2650.40</i>
8	REAR DOOR OUTER SEAL - LH <i>m/</i>	1	\$	159.00 <i>127.20</i>
9	REAR DOOR CATCH <i>bt/</i>	1	\$	141.00 <i>112.80</i>
10	REAR SILL PANEL SEAL - LH <i>xnn</i>	1	\$	159.00
11	REAR DOOR HINGE HALF UPPER PART - LH LOWER <i>xnn</i>	1	\$	54.00
12	REAR DOOR HINGE HALF UPPER PART - LH UPPER <i>xnn</i>	1	\$	51.00
13	REAR DOOR HINGE HALVES - LH UPPER <i>xnn</i>	1	\$	56.00
14	REAR DOOR HINGE HALF LOWER PART - LH LOWER <i>xnn</i>	1	\$	57.00
15	REAR DOOR COVER - LH <i>su/</i>	1	\$	286.00 <i>228.80</i>
16	REAR BUMPER <i>repair</i>	1	\$	1,839.00
17	REAR BUMPER FIXING PARTS <i>xnn</i>	1	\$	230.00
18	REAR BUMPER SPOILER <i>su/</i>	1	\$	540.00 <i>431.60</i>
19	REAR BUMPER REFLECTOR - LH <i>xnn</i>	1	\$	49.00
20	REAR WHEEL COVER - LH / RH <i>su/</i>	2	\$	598.00 <i>478.40</i>
SUB TOTAL SPARE PARTS		:	\$	11,854.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLK 2967 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL COVER - LH <i>X N N</i>	1	\$	299.00
22	SUNDRIES <i>7. ncc</i>		\$	400.00 <i>16.96</i>
TOTAL SPARE PARTS		:	\$	12,553.00
TOTAL LABOUR CHARGES		:	\$	10,352.00
GRAND TOTAL		:	\$	22,905.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

REAR LH RIM - polished

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Rasm - Hp 90010068
08/03/23 @ 1540

6 days
EXCESS: TBA

Revert
Resurvey before rent

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: