

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 10 Mar 2023

Preliminary Advice

Vehicle No	: SMS3706Z	Accident Date	: 25/02/2023
Make	: HONDA FIT	Policy No.	: SP2003972742
Assignment Date	: 09/03/2023	Excess	: S\$2,000.00
Date of Inspection	: 10/03/2023	Est. Duration of Repair	: 28
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	70,236.00
Revised Amount	:S\$	55,406.00
Check Items (Estimated)	:S\$	11,996.00
Total	:S\$	67,402.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	25,673.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,327.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING FOR SOME PARTS PRICES.
KINDLY ADVISE THE REPAIR COST OFFER TO WORKSHOP.