



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

Company Reg No 200609327M

GST Reg No MR-8500111-X

ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
KATONG HAIR-CUT & CURL SALON		Cust No/Name	/ KATONG HAIR-CUT & CURL SALON
1 BROOKE ROAD		Reg No/Reg Date	GBK4566B / 06/08/2020
#B1-11 KATONG PLAZA		Date In/Mileage	03/03/2023/ 0
SINGAPORE 429979		Chassis No	VR7EFYHZRLJ662679
Contact No	Mobile: 98658268	Engine No	10Q4DR0017317
		Make/Model	CITCV/K9 BERLINGO L2 1.5 BLUEHDI 130 EAT
		Colour/Trim	WPP BLANC BANQUISE / GY GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/03/2023/ 08:48	TLK	282 / Kevin Leong	19932

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRONT BUMPER PANEL, SUPPORT & AFFECTED AREA				2280.00
E PNT98000 PAINT WORK ON FRONT BUMPER PANEL				1100.00
E PNT88000 REMOVE & INNSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				200.00
A 55900099 VACUUM & TOP UP AIRCON GAS				500.00
E PNT88000 REPLACE REAR BUMPER, BOTH REAR TAILGATE, END PANEL & AFFECTED AREA				5320.00
E PNT98000 PAINT WORK ON REAR BOTH TAILGATE & END PANEL				1650.00
E PNT88000 REMOVE & REPLACE REAR PARKING ASSIST FOR FACILITATE REPAIR				150.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				200.00
E PNT88000 TO TRANSFER BOTH REAR TAILGATE ATTACHMENTS TO NEW PANEL				400.00
E PNT88000 TO REMOVE & REPLACE ON REAR LH TAILGATE GLASS				500.00
E PNT88000 TO REMOVE & REPLACE ON REAR RH TAILGATE GLASS				500.00
M SUNDRY TO APPLY BOTH REAR TAILGATE GLASS SEALANT				180.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA				320.00
M SUNDRY PERFORM RUST PREVENTION				320.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				150.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				380.00
M SUNDRY				80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

Company Reg No 200609327M
 GST Reg No MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
KATONG HAIR-CUT & CURL SALON	Cust No/Name / KATONG HAIR-CUT & CURL SALON
1 BROOKE ROAD	Reg No/Reg Date GBK4566B / 06/08/2020
#B1-11 KATONG PLAZA	Date In/Mileage 03/03/2023/ 0
SINGAPORE 429979	Chassis No VR7EFYHZRLJ662679
Contact No Mobile: 98658268	Engine No 10Q4DR0017317
	Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 130 EAT
	Colour/Trim WPP BLANC BANQUISE / GY GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
C5M00073	Cash	04/03/2023/ 08:48	TLK	282 / Kevin Leong	19932

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
TO SUPPLY STICKER '70KM/H'				80.00
M SUNDRY				
TO SUPPLY STICKER '6 PAX'				680.00
M SUNDRY				
TO SUPPLY REAR LH REAR TAILGATE GLASS				680.00
M SUNDRY				
TO SUPPLY REAR RH TAILGATE GLASS				60.00
M SUNDRY				
TO SUPPLY C & C EMBLEM				120.00
M SUNDRY				
TO SUPPLY FRT & REAR NUMBER PLATE WITH FRAME				50.00
M SUNDRY				
SUNDRIES				
M FRONT BUMPER INF	1.00	955.00	0.00	955.00
M FR BMPR GRILLE	1.00	619.00	0.00	619.00
M FRONT BUMPER	1.00	858.00	0.00	858.00
M ARMATURE P	1.00	322.00	0.00	322.00
M BUMPER BRACKET LH LAT	1.00	171.00	0.00	171.00
M BUMPER BRACKET RH LAT	1.00	171.00	0.00	171.00
M BUMPER ABSORBER	1.00	234.00	0.00	234.00
M SET REINFORFORC	1.00	246.00	0.00	246.00
M BUMPER CROSSMBR AV ASS	1.00	492.00	0.00	492.00
M FIXING STUD	1.00	145.00	0.00	145.00
M FACE CROSSMEMBR SUP	1.00	322.00	0.00	322.00
M BUMPER CROSSMBR AV ASS	1.00	492.00	0.00	492.00
M FIX MINICH	1.00	405.00	0.00	405.00
M REAR BUMPER	1.00	771.00	0.00	771.00
M RECESS DOOR	1.00	105.00	0.00	105.00
M OVERRIDER LH	1.00	546.00	0.00	546.00
M OVERRIDER RH	1.00	546.00	0.00	546.00
M BUMPER BRACKET LH LATERAL	1.00	227.00	0.00	227.00
M BUMPER BRACKET RH LATERAL	1.00	227.00	0.00	227.00
M BUMPER BRACKET LH SUPERIEUR	1.00	171.00	0.00	171.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



CITROËN

Company Reg No 200609327M
GST Reg No MR 8500111 X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
KATONG HAIR-CUT & CURL SALON	Cust No/Name / KATONG HAIR-CUT & CURL SALON
1 BROOKE ROAD	Reg No/Reg Date GBK4566B / 06/08/2020
#B1-11 KATONG PLAZA	Date In/Mileage 03/03/2023/ 0
SINGAPORE 429979	Chassis No VR7EFYHZRLJ662679
Contact No Mobile: 98658268	Engine No 10Q4DR0017317
	Make/Model CITCV/K9 BERLINGO L2 1.5 BLUEHDI 130 EAT
	Colour/Trim WPP BLANC BANQUISE / GY GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	04/03/2023/ 08:48	TLK	282 / Kevin Leong	19932

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BUMPER BRACKET RH SUPERIEUR	1.00	171.00	0.00	171.00
M BUMPER CROSSMBR AR - ASS	1.00	691.00	0.00	691.00
M FIXING STUD	1.00	193.00	0.00	193.00
M SIDE DOOR LH AR	1.00	2391.00	0.00	2391.00
M SIDE DOOR RH AR	1.00	2471.00	0.00	2471.00
M DOOR HINGES	1.00	388.00	0.00	388.00
M DOOR HINGES	1.00	388.00	0.00	388.00
M WEATHERSTRIP	1.00	321.00	0.00	321.00
M DOOR SEAL	1.00	139.00	0.00	139.00
M WATER JET SEAL	1.00	103.00	0.00	103.00
M ADHESIVE KIT	1.00	39.00	0.00	39.00
M FIX PORTES	1.00	132.00	0.00	132.00
M BADGE	1.00	117.00	0.00	117.00
M BADGE	1.00	91.00	0.00	91.00
M TAIL-LIGHT RH	1.00	268.00	0.00	268.00
M TAIL-LIGHT LH	1.00	268.00	0.00	268.00
M STOP LIGHT	1.00	113.00	0.00	113.00
M LICEN PLAT LAMP	1.00	36.00	0.00	36.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Parts	16,345.00
Labour	13,330.00
Standard Menu	0.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	2,570.00
Total (w/o GST)	32,245.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.