

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 13 Mar 2023

**Preliminary Advice**

Vehicle No	: SMR4296M	Accident Date	: 02/03/2023
Make	: HYUNDAI AVANTE	Policy No.	: DMHCSNW00000302301
Assignment Date	: 10/03/2023	Excess	: S\$1,250.00
Date of Inspection	: 10/03/2023	Est. Duration of Repair	: 12
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	19,786.11
Revised Amount	:S\$	16,170.51
Check Items (Estimated)	:S\$	3,455.00
Total	:S\$	19,625.51
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	27,901.00
Salvage Value	:S\$	
Margin for Repair	:S\$	50,099.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO SECOND HAND PARTS AVAILABLE. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.