LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

From:

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three Singapore 038988

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

LKK Auto Consultants Pte Ltd

13 Mar 2023 Attn: Date:

Preliminary Advice

Vehicle No : SLG4449J Accident Date : 24/02/2023 Make : BMW 318I Policy No. : DMPG22010892

Assignment Date : 09/03/2023 **Excess** : S\$0.00 Date of Inspection Est. Duration of Repair : 9

: 10/3/2023 Inspection At : YK SUPREME AUTOWERKZ PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32.283.25
Revised Amount	:S\$	18,639.20
Check Items (Estimated)	:S\$	3,198.40
Total	:S\$	21,837.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	76,000.00
COE / PARF Rebate	:S\$	24,588.00
0.1	0.0	

Salvage Value :S\$

Margin for Repair :S\$ 51,412.00

Remarks

(X	• ,	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Lump Sum Repair