



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302156

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/04/2023
Reference CC6/CTI23002537/Uya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNG 9552L
Insured Veh. GBC 9102R
Claim No. SNM23D201819/C02
Policy No. DMCVSNW00146282201
Accident Date 09/03/2023
Inspection Date 10/03/2023

Description	Total
Third Party Express Settlement	280.00
Subtotal	280.00
GST (8%)	22.40
Grand Total	302.40

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI23002537/Uya3q2 Date: 09/04/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 9102R	Veh. Inspected	SNG 9552L
	Policy No.	DMCVSNW00146282201	Coverage (\$)	0.00
	Claim No.	SNM23D201819/C02	Excess (\$)	0.00
	Assign From		Assign Date	10/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	LEXUS GS300 (A)	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JTHBH96S505060551	Colour	WHITE
	Odometer	182925 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/03/2023	Inspection Date	10/03/2023
	Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 9552L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	198.50	-
1	FRONT FENDER (N/S)	BUCKLED	1,208.00	945.10
2	FRONT BUMPER SIDE RETAINER @\$72.30	NOT NECESSARY	144.60	-
1	FRONT DOOR WING MIRROR COVER LH	NOT NECESSARY	235.00	-
1	FRONT DOOR WING MIRROR ASSY LH	NOT NECESSARY	1,787.00	-
1	FRONT DOOR LH	BADLY DENTED	1,815.00	1,815.00
1	FRONT DOOR RUBBER LH	TWISTED / NECESSARY	227.00	227.00
1	FRONT DOOR FRAME BLACK TAPE LH	NECESSARY	90.00	90.00
1	FRONT DOOR TOP HINGES LH	BENT	95.90	95.90
1	FRONT DOOR CHECK LH	BENT	95.90	95.90
1	FRONT DOOR INNER LOCK LH	NOT NECESSARY	131.80	-
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	792.80	-
1	FRONT DOOR OUTER HANDLE BASE LH	NOT NECESSARY	191.60	-
1	FRONT DOOR OUTER HANDLE KNOB LH	NOT NECESSARY	147.00	-
1	FRONT DOOR GLASS REGULATOR LH	NOT NECESSARY	101.90	-
1	FRONT DOOR GLASS REGULATOR MOTOR LH	NOT NECESSARY	345.50	-
1	FRONT DOOR GLASS CHANNEL LH	NOT NECESSARY	688.40	-
1	FRONT DOOR CHANNEL BRACKET LH	NOT NECESSARY	220.00	-
1	FRONT DOOR BOARD LH	NOT NECESSARY	912.80	-
1	FRONT DOOR GLASS OUTER MOULDING LH	BENT	227.00	227.00
1	FRONT DOOR PILLAR LH	TO REPAIR SEE LABOUR	655.00	-
1	FRONT WINDSCREEN GLASS MOULDING	NOT NECESSARY	72.60	-
2	FRONT ABSORBER LH @\$393.80	NOT NECESSARY	787.60	-
2	FRONT LOWER ARM LH @\$479.20	NOT NECESSARY	958.30	-
2	FRONT KNUCKLE ARM LH @\$606.30	NOT NECESSARY	1,212.60	-
2	FRONT DRIVE SHAFT LH @\$958.00	NOT NECESSARY	1,916.00	-
	LESS 10% DISCOUNT		-1,525.78	-349.59
			13,732.02	3,146.31

Report Ref No. CC6/CTI23002537/Uya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
2	FRONT TYRE LH (SN)	NOT NECESSARY	500.00	-
2	FRONT SPORT RIM LH (SN)	NOT NECESSARY	1,500.00	-
6	FRONT FENDER INNER GARNISH CLIPS @\$12.90 (SN)	NOT NECESSARY	77.40	-
			2,077.40	-
	<u>LABOUR</u>			
	TO CHECK WIRING.		150.00	20.00
	APPLY ANTI RUST .		200.00	60.00
	REMOVE & REFIX CUSHION UPHOLSTERY .	NOT NECESSARY	250.00	-
	REMOVE AND REFIX FRONT CARRIAGE ,SUSPENSION SYSTEM.	NOT NECESSARY	600.00	-
	CHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACE PARTS .INCLUSIVE OF THE REPAIR OF FRONT DOOR PILLAR LH		2,500.00	300.00
	TO SPRAY PAINTING.		2,000.00	600.00
			5,820.00	980.00
GRAND TOTAL			21,629.42	4,126.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC6/CTI23002537/Uya3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNG 9552L

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNG 9552L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SNG 9552L

RE-INSPECTION

