



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 08-03-2023

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : GBE5824G

ACCIDENT DATE : 06-03-2023 08:00

THIRD PARTY REF. : YP6507K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE GBE5824G TOYOTA HIACE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BONNET	230.00 <i>bt</i>
2	1	FRONT BONNET EMBLEM	30.00 <i>ad</i>
3	1	FRONT BONNET LOCK	45.00 <i>Rx</i>
4	1	FRONT SUPPORT PANEL	135.00 <i>Rx</i>
5	1	FRONT BRACCE PANEL	25.00 <i>X</i>
6	2	FRONT SUPPORT LOWER BRACKET@\$70.00	140.00 <i>X</i>
7	2	FRONT HEADLAMP@\$245.00	<i>LHX</i> 490.00 <i>RH on</i>
8	1	FRONT GRILLE BASE	175.00 <i>cur</i>
9	1	FRONT GRILLE TOP	80.00 <i>int</i>
10	1	FRONT GRILLE LOWER	125.00 <i>?</i>
11	1	FRONT CORNER PANEL RH	60.00 <i>bt</i>
12	1	FRONT BUMPER	200.00 <i>fy</i>
13	1	FRONT BUMPER TOP BEAM	75.00 <i>X</i>
14	1	FRONT BUMPER VERTICAL BRACKET	35.00 <i>X</i>
15	1	FRONT BUMPER REINFORCEMENT	125.00 <i>bt</i>
16	1	FRONT BUMPER LOWER GRILLE	65.00 <i>?</i>
17	1	FRONT BUMPER SIDE RBACKET	55.00 <i>cur</i>
18	1	FRONT BUMPER SIDE FUESE COVER RH	45.00 <i>cur</i>
19	10	FRONT BUMPER CLIP @\$2.50	25.00 <i>ad</i>
20	1	INETR cooler	480.00 <i>X</i>
21	1	INTERCOOLER GARNISH TOP	40.00 <i>X</i>
22	1	INTERCOOLER GARNISH LOWER	50.00 <i>X</i>
23	1	WASHER TANK	35.00 <i>X</i>
24	1	SPARE TANK	155.00 <i>X</i>
25	1	AIR CLEANER BOX	240.00 <i>?</i>



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

VEHICLE NO. : GBE5824G
ACCIDENT DATE : 06-03-2023 08:00
THIRD PARTY REF. : YP6507K

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
			3,160.00
		ADD 10 %	316.00
		TOTAL (A)	3,476.00

SPECIAL NETT ITEMS

1	1	COMPANY PROFILE RH	15.00 <i>na</i>
2	1	FRONT NUMBER PLATE	40.00 <i>4-30</i>
		TOTAL (C)	55.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	50.00 <i>30</i>
2	1	TO REMOVE/REFIT/REFILL AIR CON GAS	120.00 <i>100?</i>
3	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	850.00 <i>700</i>
4	1	SPRAYPAINTING CHARGES	850.00 <i>600</i>
		TOTAL (D)	1,870.00

ESTIMATE TOTAL

5,401.00

Taufm 99495749 / 62583561
WP 10/3/23 C 1030

05 days
Taufm C11hantoum
P/P Resury before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: