



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002544/Rny3e2 Date: 02/08/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 5147S	Veh. Inspected	XB 7882E	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/0751	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	09/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	HINO FS1ELKD 28 TON 6X4 MT	c.c	12913	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JHDFS1ELKXXX12430	Colour	WHITE	
Odometer	5865 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	295/80 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2023	Inspection Date	10/03/2023	
Survey held at	CONVINCE ENGINEERING PTE LTD 29 FIRST LOK YANG ROAD, SINGAPORE 629736			
5a. Remarks				
A)REGISTRATION DATE: 15 AUG 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	