Immediate Advice

To : HSBC LIFE (SINGAPORE) PTE LTD DATE: 15/3/2023

Survey details

Date of loss	3/3/2023
Date of appointment	10/3/2023
Date of survey	10/3/2023
Location of survey	LUCK7WIN PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	SLG 4070S
Make and Model	TOYOTA HARRIER 2.0 PREMIUM AT
Date of registration	29/9/2016
Excess	
Market Value	\$74,000.00
Parf Rebate	\$42,526.00
Nett Loss	\$31,474.00

Repair details

Initial Estimata	
Initial Estimate	

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (estimated)	
N	4 1 (+:+-1)

Number of days of repair 4 days (estimated)

Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$3,100.00-\$4,000.00