



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: KHOR SAW THENG			Ref: CS/HSB23002548/Aqy3m4 Date: 22/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 102D	Veh. Inspected	SCR 76B	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S3M04KAQ	Excess (\$)	0.00	
Assign From	KHOR SAW THENG	Assign Date	10/03/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLA200	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDC1569432J606244	Colour	BRONZE	
Odometer	38675 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	DUNLOP	6 mm	
L/H Front Tyre	235/50 R18	DUNLOP	6 mm	
R/H Rear Tyre	235/50 R18	DUNLOP	6 mm	
L/H Rear Tyre	235/50 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/03/2023	Inspection Date	10/03/2023	
Survey held at	TSL AUTO GARAGE BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	